

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 22 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU Peirce Canyon 17 Federal #1H (2RP-1266)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-36635
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 17	Township 25S	Range 30E	Feet from the 350	North/South Line South	Feet from the 350	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.123902 Longitude W 103.896282

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 10 bbls.	Volume Recovered: None
Source of Release: A 3" line going from the process vessels to the tanks.	Date and Hour of Occurrence: 7/31/12 Approximately 12:00 p.m.	Date and Hour of Discovery: 7/31/12 at 2:20 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour: 7/31/12 2:27 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 3" line going from the heater to the tanks split at a seam in the pipe. The entire section of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.*
The split was on top of the pipe, the released fluid misted an area covering approximately 36,000 sq.ft. There was less than 1/4" of soil saturation out to a distance of 300 ft. from the release point. The vegetation had a very slight mist out to a total distance of 420 ft. The area affected appears to have been a frak pond used during the drilling operations. The reclaimed area measured approximately 375 ft. East by West and 510 ft. North by South. The affected area will be remediated in accordance to the NMOCD and BLM guidelines.
DFSI was retained by BOPCO, L.P. during a time frame of 12/2/13 to 2/18/14, approximately 60 cubic yards of soil was hauled to Lea Land. Reference the Site Closure Report dated 6/17/14.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: 9/29/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 9/19/14	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-1266