

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 02 2014

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

nAB1427548938 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: McIntyre B #7	Facility Type: Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31561
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	20	17S	30E	660'	South	660'	West	Eddy

Latitude 32.8137724103499 Longitude -104.001670530599

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5 bbls Oil ; 10 bbls PW	Volume Recovered: 3 bbls Oil ; 8 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 9/15/2014 1:00 pm	Date and Hour of Discovery: 9/15/2014 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by corroded flowline. Repairs were made to the line and a vacuum truck was dispatched to pick up all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The impacted area occurred at the NE corner of the location and ran into the pasture. The area was treated with microblaze. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

A. Trujillo

Printed Name: Amanda Trujillo

Approved by Environmental Specialist:

H. P.

Title: Senior Environmental Coordinator

Approval Date: 10/2/14

Expiration Date:

NA

E-mail Address: atrujillo@concho.com

Conditions of Approval:

Attached ☐

Date: October 2, 2014

Phone: 575-748-6940

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 11/2/14

2RP-2519

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Thursday, October 02, 2014 11:49 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jlrobertson@blm.gov
Subject: (Notification/Initial C-141) McIntyre B #7(30-015-31561)
Attachments: 09-15-2014 McIntyre B #7 (FL) Initial.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release at the **McIntyre B #7(30-015-31561)**.

Unit M Section 20 Township 17S Range 30E

The release occurred at 1:00 pm on 09/15/2014.

Released: 5 bbls Oil; 10 bbls PW

Recovered: 3 bbls Oil; 8 bbls PW

This release was caused by a corroded flowline. The release occurred on the NE edge of the pad and ran into the pasture. Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.