NM OIL CONSERVATION

OCT 07 2014

Form C-141 Revised August 8, 2011

ARTESIA DISTRICT

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico District II 811 S. First St., Artesia, NM 88210 District III **Energy Minerals and Natural Resources** 1000 Rio Brazos Road, Aztec, NM 87410 **District IV**

1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1AB142815 6408	OPERATOR Initial Report Final Report
Name of Company: Mewbourne Oil Company 4144	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Delaware Ranch SWD #001	Facility Type: SWD
Surface Owner: Private Mineral Owner	er: N/A API No. 30-015-22734
-	ION OF RELEASE
1 1 1 2 1	orth/South Line Feet from the East/West Line County East Eddy
Latitude 32.051632	2 Longitude104.0513889
NATUR	RE OF RELEASE
Type of Release: Produced water/Oil	Volume of Release: estimated 310 Volume Recovered: Oil (135 bbls) bbls total, fluid PW(170 bbls) PW(170 bbls)
Source of Release: Water Tank	137 oil 173 PW Date and Hour of Occurrence Date and Hour of Discovery
Tank	10-2-14 10-2-14 7:00 am
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Requir	If YES, To Whom? Heather Patterson
By Whom? Zack Thomas	Date and Hour 10-3-14 10:30 am
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*	
Cause of the leak- SWD pump was down due to electrical problem (bl	olown fuse) and a valve was also left open on unloading station. Pumper shut valve nump back online.
Cause of the leak- SWD pump was down due to electrical problem (blupon arrival to stop leak and electrician fixed blown line fuse to get pure Describe Area Affected and Cleanup Action Taken.* Affected area- Secondary containment and southwest side of well page	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all
Cause of the leak- SWD pump was down due to electrical problem (blupon arrival to stop leak and electrician fixed blown line fuse to get publication arrival to stop leak and electrician fixed blown line fuse to get publication.* Describe Area Affected and Cleanup Action Taken.* Affected area- Secondary containment and southwest side of well paratanding fluid inside the secondary containment and on the bermed parapproved NMOCD disposal site. hereby certify that the information given above is true and complete.	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an
Cause of the leak- SWD pump was down due to electrical problem (blupon arrival to stop leak and electrician fixed blown line fuse to get pure Describe Area Affected and Cleanup Action Taken.* Affected area- Secondary containment and southwest side of well parstanding fluid inside the secondary containment and on the bermed parapproved NMOCD disposal site. Thereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remember the environment. In addition, NMOCD acceptance of a C-141 report	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an to the best of my knowledge and understand that pursuant to NMOCD rules and ase notifications and perform corrective actions for releases which may endanger by the NMOCD marked as "Final Report" does not relieve the operator of liability ediate contamination that pose a threat to ground water, surface water, human health ort does not relieve the operator of responsibility for compliance with any other
Describe Area Affected and Cleanup Action Taken.* Affected area- Secondary containment and southwest side of well parstanding fluid inside the secondary containment and on the bermed parapproved NMOCD disposal site. Thereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remer	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an eto the best of my knowledge and understand that pursuant to NMOCD rules and ase notifications and perform corrective actions for releases which may endanger by the NMOCD marked as "Final Report" does not relieve the operator of liability ediate contamination that pose a threat to ground water, surface water, human health
Cause of the leak- SWD pump was down due to electrical problem (blapon arrival to stop leak and electrician fixed blown line fuse to get purpose to be a standing fluid inside the secondary containment and southwest side of well parapproved NMOCD disposal site. Thereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedor the environment. In addition, NMOCD acceptance of a C-141 reported and/or regulations.	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an ease notifications and perform corrective actions for releases which may endanger by the NMOCD marked as "Final Report" does not relieve the operator of liability ediate contamination that pose a threat to ground water, surface water, human health ort does not relieve the operator of responsibility for compliance with any other OIL CONSERVATION DIVISION Signed By
Cause of the leak- SWD pump was down due to electrical problem (blapon arrival to stop leak and electrician fixed blown line fuse to get purpose to get purpose the standing fluid inside the secondary containment and southwest side of well particularly fluid inside the secondary containment and on the bermed particularly fluid inside the secondary containment and on the bermed particularly fluid inside the secondary containment and on the bermed particularly fluid inside the secondary containment and on the bermed particularly fluid inside the secondary containment and on the bermed particularly fluid inside the secondary containment and on the bermed particularly fluid inside the secondary containment and complete regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedor the environment. In addition, NMOCD acceptance of a C-141 report of the environment. In addition, NMOCD acceptance of a C-141 report of the environment. In addition, NMOCD acceptance of a C-141 report of the environment. In addition, NMOCD acceptance of a C-141 report of the environment. In addition, NMOCD acceptance of a C-141 report of the environment.	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an eto the best of my knowledge and understand that pursuant to NMOCD rules and ase notifications and perform corrective actions for releases which may endanger by the NMOCD marked as "Final Report" does not relieve the operator of liability ediate contamination that pose a threat to ground water, surface water, human health ort does not relieve the operator of responsibility for compliance with any other OIL CONSERVATION DIVISION
Cause of the leak- SWD pump was down due to electrical problem (blupon arrival to stop leak and electrician fixed blown line fuse to get pure Describe Area Affected and Cleanup Action Taken.* Affected area- Secondary containment and southwest side of well parstanding fluid inside the secondary containment and on the bermed parapproved NMOCD disposal site. Thereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remember the environment. In addition, NMOCD acceptance of a C-141 report	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an ease notifications and perform corrective actions for releases which may endanger by the NMOCD marked as "Final Report" does not relieve the operator of liability ediate contamination that pose a threat to ground water, surface water, human health ort does not relieve the operator of responsibility for compliance with any other OIL CONSERVATION DIVISION Signed By
Cause of the leak- SWD pump was down due to electrical problem (blupon arrival to stop leak and electrician fixed blown line fuse to get purpose to get purpose and the standing fluid inside the secondary containment and southwest side of well partially fluid inside the secondary containment and on the bermed parapproved NMOCD disposal site. Thereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedor the environment. In addition, NMOCD acceptance of a C-141 report dederal, state, or local laws and/or regulations. Signature: Printed Name: Zack Thomas Fittle: Environmental Rep.	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an et of the best of my knowledge and understand that pursuant to NMOCD rules and ase notifications and perform corrective actions for releases which may endanger by the NMOCD marked as "Final Report" does not relieve the operator of liability ediate contamination that pose a threat to ground water, surface water, human health ort does not relieve the operator of responsibility for compliance with any other OIL CONSERVATION DIVISION Signed By Approved by Environmental Specialist: Expiration Date: NA Conditions of Approval:
Cause of the leak- SWD pump was down due to electrical problem (blupon arrival to stop leak and electrician fixed blown line fuse to get purpose to stop leak and electrician fixed blown line fuse to get purpose to stop leak and electrician fixed blown line fuse to get purpose to stop leak and electrician fixed blown line fuse to get purpose to stop leak and complete to stop leak and in the secondary containment and on the bermed parapproved NMOCD disposal site. Thereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain release to the stop leak to the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedor the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations. Signature: Printed Name: Zack Thomas Fitle: Environmental Rep. E-mail Address: zthomas@mewbourne.com	ad surface (entire pad has 2' earth berm). Vacuum truck moved in and recovered all ad surface. Contaminated soil on pad surface will be removed and hauled to an est to the best of my knowledge and understand that pursuant to NMOCD rules and as enotifications and perform corrective actions for releases which may endanger by the NMOCD marked as "Final Report" does not relieve the operator of liability ediate contamination that pose a threat to ground water, surface water, human health ort does not relieve the operator of responsibility for compliance with any other OIL CONSERVATION DIVISION Signed By Approved by Environmental Specialist: Expiration Date: NA Expiration Date: NA

Bratcher, Mike, EMNRD

From: Zack Thomas < zthomas@mewbourne.com>

Sent: Tuesday, October 07, 2014 8:00 AM

To: Bratcher, Mike, EMNRD Subject: C141- Delaware Ranch SWD

Attachments: C141- Delaware Ranch SWD #001 (10-2-14) initial.doc

Zack Thomas

Mewbourne Oil Company

PO Box 5270

Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252 (575) 602-2188

Email: zthomas@Mewbourne.com

222-2624