NM OIL CONSERVATION

ARTESIA DISTRICT

District I . 1625 N. French Dr., Hobbs, NM 88240 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV. 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

OCT 1 5 2014

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rele	ease Notific	catio	n and Co	rrective A	ction			
NABI			•			OPERA			⊠ Initia	al Report Final Report	
				RCES II-A, LP	<i>3775</i>						
Address: 1:	Address: 1111 Bagby Street Suite 4600, Houston, TX 77002 Telephone No.: 575-623-8424										
Facility Nat	ne: Wind	lfohr 4 Fede	ral #2 Ba	ittery		Facility Type: Battery					
Surface Owner : Bogle Farms Mineral Owner:						BLM			API #30-015-30411 Lease No. # MNL-061783A		
	LOCATION OF RELEASE										
Unit Letter I	, , , , , , , , , , , , , , , , , , , ,					/South Line	Feet from the	East/W	ast/West Line County Eddy		
			Latituc	le <u>32.775006</u>	N	Longitud	e <u>-104.27607</u>	7 W	_		
NATURE OF RELEASE											
Type of Rele						Volume of	Volume of Release: 45 bbls PW Volume Recovered: 15 bbls PW			Recovered: 15 bbls PW	
Source of Release : Surface Flow Line						1	e and Hour of Occurrence: Date and Hour of Discovery: 10/13/ 13/14 3:00 pm Date and Hour of Discovery: 10/13/				
Was Immedi	ate Notice (***************************************	If YES, To Whom?					
		×	Yes [No Not R	cquircd	BLM/Jeffery Robertson & OCD/Mike Bratcher					
		Wilson with T	alon/LPE)		Date and Hour: 10/13/14 @ 4:00 pm					
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.					
If a Watercon	irse was In	pacted, Descr	ibe Fully.		~	<u> </u>	· ·				
45 barrels of was repaired Describe Are	f produced d. Talon/L a Affected	water. A vac PE was conta and Cleanup A	c truck w acted for i Action Tal	as immediately o nitial site assess ken.*∐The initia	alled to ment ar I releas	the site and id to generate e point measi	recovered 15 bai e a work plan. ired approximat	rrels. Al	eet long by	re driver causing a release of ere shut in and the flow line y 21-feet wide then flowed east erm the flow path to prevent	
further mig											
regulations a public health should their or or the enviro	Il operators or the envi operations l nment. In a	are required to ronment. The nave failed to	o report and acceptant adequately OCD acceptant	nd/or file certain ce of a C-141 rep investigate and	release i ort by thremedia	notifications a ne NMOCD nate contaminat	nd perform correct arked as "Final Ricon that pose a three the operator of	etive action teport" do reat to gro responsi	ons for rel oes not rel ound wate bility for c	suant to NMOCD rules and leases which may endanger lieve the operator of liability or, surface water, human health compliance with any other	
Signature: Mily Bal							OIL CONSERVATION DIVISION				
Printed Name: Michael Barrett							District Supervis	/_/	ho	h	
Title: Production Supervisor							Approval Date: / U// Expiration Date: NA				
E-mail Addr	ess: mbarı	rett@limeroc	kresource	s.com		Conditions of Approval: Attached					
Date: 10/15	5/2014		one: 575-	623-8424			per O.C.D.			elines	
Attach Addi	tional She	ets If Necess	sary			TER THA	WEDIATION N:	14"		2RP-2563	

Patterson, Heather, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>

Sent: Wednesday, October 15, 2014 3:30 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Robertson, Jeffery

Cc: Michael Barrett; David Adkins

Subject: Windfohr 4 Federal #2 * 30-015-30411 * Lease No. MNL-061783A * DOR 10/13/2014

Attachments: Windfohr 4 Fed #2 Btty C-141_10-15-14.pdf

Attached please find the initial C-141 on the above referenced release.

Thank you.

Kimberly M. Wilson

Project Manager Talon/LPE 408 West Texas Avenue Artesia, New Mexico 88210 Office: 575.746.8768

Fax: 575.746.8905 Cell: 575.602.3826 Emergency: 866.742.0742 Email: kwilson@talonlpe.com Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist

Staples Foundation for Learning Hall of Fame Recipient:2010 ICIC and Business Week-Top 100: 2010, 2009, 2008, 2007, 2006

Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

ENVIRONMENTAL RELEASE NOTIFICATION Call-In Sheet

Date: 10/13/14		<u>,</u>
DAVID AdKins (Person Reporting)	from Talon +	or CimeRock
is reporting a release at the <u>Wind</u> (Site)	fohr 4 Fed #	2
api# <u>015-30411</u> ,	Sec. 4 T 185 - R 27E	•
(
Occurred on:(Date of Occurrence)	at <u>AM/PN</u> (Time of Occurrence)	<u>1.</u>
Volume released: Initial est.	45 hbls Pul	C-141 received: 1015 4
Volume recovered:		2RP- 2563
Briefly Describe Cause of Problem and	d action taken:	
		1.5.5
		. (
		(Initials)
**********		**************************************
	FLARE NOTIFICA Call-In Sheet	
	Cuil-III Sheet	
Date:		
Poport Flare for	from	
Report Flare for	from	Person Reporting)
(Reporting Company)	(1)	Person Reporting)
(Reporting Company) Occurred on:at	AM/PM.	·
(Reporting Company)	(1)	Person Reporting) C-129/C-141 received:
(Reporting Company) Occurred on:at	AM/PM. (Time of Occurrence)	C-129/C-141 received:
(Reporting Company) Occurred on:at (Date) Flared Inlet Gas for:	AM/PM. (Time of Occurrence)	C-129/C-141 received:
(Reporting Company) Occurred on:at (Date)	AM/PM. (Time of Occurrence)	C-129/C-141 received:
(Reporting Company) Occurred on:at (Date) Flared Inlet Gas for: Total MCF:	AM/PM. (Time of Occurrence)	C-129/C-141 received;
(Reporting Company) Occurred on:at (Date) Flared Inlet Gas for: Total MCF:	AM/PM. (Time of Occurrence)	C-129/C-141 received:
(Reporting Company) Occurred on:at (Date) Flared Inlet Gas for: Total MCF: Briefly Describe Cause of Problem and	AM/PM. (Time of Occurrence)	C-129/C-141 received;
(Reporting Company) Occurred on:at (Date) Flared Inlet Gas for: Total MCF: Briefly Describe Cause of Problem and	AM/PM. (Time of Occurrence)	C-129/C-141 received:
(Reporting Company) Occurred on:at (Date) Flared Inlet Gas for: Total MCF: Briefly Describe Cause of Problem and	AM/PM. (Time of Occurrence)	C-129/C-141 received: