District I	1	
1625 N.	French Dr., Hobbs, NM 8824	10
District I	<u>11</u>	
1301 W.	Grand Avenue, Artesia, NM	88210
District I	III	
1000 Ric	o Brazos Road, Aztec, NM 87	7410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

State of New Mexico **Energy Minerals and Natural Resources Oil Conservation Division** 1220 South St. Francis Dr.

MOBBSOCD

OCT 17 2014

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back RECEIVED side of form

Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

	OPERATOR	🛛 Initial Report	Final Report
Name of Company – EnerVest Operating LLC	Contact – Elroy Ardoin		
Address – 1001 Fannin Street, Suite 800, Houston, TX 77002	Telephone No. (713) 495 6534		
Facility Name – Abalone AMB State #1 Tank Battery	Facility Type – Tank Battery		

Surface Owner – State of NM	Mineral Owner

۰,

API No. 30-025-01153

LOC	ATION	OF RE	LEASE
com the	South Li	10	Feet from

Unit Letter Secti D 26	on Township 14S	Range 33E	Feet from the	South Line	Feet from the	East/West Line	County Lea
---------------------------	--------------------	--------------	---------------	------------	---------------	----------------	---------------

Latitude N 32.78634 Longitude W 104.05161

NATURE OF RELEASE						
Volume of Release estimated 100bbls	Volume Recovered 55bbls					
Date and Hour of Occurrence ? 12/8/2010 – before 3:00PM	Date and Hour of Discovery 12/8/2010 - 3:00PM					
If YES, To Whom? Larry Johnson – NMOCD Hobbs (· · · · · · · · · · · · · · · · · · ·					
Date and Hour – 12/9/10 2:30PM						
If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*						
Describe Cause of Problem and Remedial Action Taken.* A hole in the bottom of the separator was the source of the release. The spill was partially contained within the tank battery dike area. An estimated 100bbls was spilled with 45bbls being recovered. The faulty separator was repaired immediately. Repairs began immediately on the leaking separator. No further remedial action has been taken yet.						
Describe Area Affected and Cleanup Action Taken.* The spill area included the section within the tank battery dike which is 12yds X 11yds, the caliche pad area in front of the tank battery which is an estimated 15yds X 40yds area outside the berm, and the area across the location to the east side which about 12yds X 15yds. Remediation action taken was to recover about 45 bbls of freestanding produced water with some oil into a transport. A sampling investigation will be conducted to delineate the extent of contamination. A sampling report will be submitted to OCD with a remediation plan to be implemented upon NMOCD approval . The most likely remediation plan to be recommended will be to conduct "dig & haul" operation with lab analysis. A closing report will then be submitted to OCD.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
OIL CONSERVATION DIVISION						
Approved by District Supervisor	calic					
Approval Date: 10-17 - 19	Expiration Date: 12-17-17					
Conditions of Approval:	Attached					
Belinte & radiato anon	- apar IRA 3386 Ful 05-24 143199					
10 MOCO gute . Solut C-141 by 12.17-14	fail 05-12 143199 101720055929					
	Volume of Release estimated 100bbls Date and Hour of Occurrence ? 12/8/2010 – before 3:00PM If YES, To Whom? Larry Johnson – NMOCD Hobbs of Date and Hour – 12/9/10 2:30PM If YES, Volume Impacting the Wa bottom of the separator was the source billed with 45bbls being recovered. T urther remedial action has been taken 12yds X 11yds, the caliche pad area in boation to the east side which about 12 oduced water with some oil into a tra tamination. A sampling report will be "dig & haul" operation with lab analy. the best of my knowledge and underst hotifications and perform corrective an te contamination that pose a threat to loes not relieve the operator of resport OIL CONSER Approved by District Supervisor. Approval Date: 10~17 - 19					

ogad	. 143199
NTO 17.	1055929
0 TO 142	28

OCT 17 2014