

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

OCT 23 2014

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Prize 27 Federal #2	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-31902

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	22S	32E	660'	South	660'	East	Lea

Latitude N 32.35709° Longitude W 103.65617°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	70 bbls	Volume Recovered	60 bbls
Source of Release	loss of power to transfer pump caused a tank to over spill	Date and Hour of Occurrence	04/1/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen-BLM, Jim Amos-BLM and Geoffrey Leking-OCD		
By Whom?	Chancey Summers	Date and Hour	04/2/2013 @ 10:02 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Loss of power to transfer pump caused a tank to over spill 70 bbls of produced water to leak onto the ground. 60 bbls of produced water were recovered via vacuum truck and power was restored.

Describe Area Affected and Cleanup Action Taken.*
The area affect was appx. 85' by 35'. Loss of power to transfer pump caused a tank to over spill 70 bbls of produced water to leak onto the ground. 60 bbls of produced water were recovered via vacuum truck and power was restored. Remediation will be performed in accordance with an approved plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by District Supervisor: <i>Tom Spee</i>		
Title: HES Specialist	Approval Date: 10-23-14	Expiration Date: —	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 4/8/13	Phone: (575) 397-8216	1 RP-3392	

* Attach Additional Sheets If Necessary

16696
ATO 1429.63 1864
PTI 1429.63 1964
OCT 27 2014