

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

NOV 01 2014

RECEIVED

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company GMT Exploration	Contact B.J. Cox
Address 1560 Broadway, STE 2000, Denver, Co. 80202	Telephone No. 720-946-3028
Facility Name Merchant Gap 25 Sate com IH	Facility Type Oil Well

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	API No. 30-025-41450
-----------------------------------	-----------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	25	22S	34E	40	South	350	West	Lea

Latitude N 32 21'19.93" Longitude W 103 25'52.13"

NATURE OF RELEASE


Type of Release Oil	Volume of Release 40 bbls Est.	Volume Recovered 40 bbls Est.
Source of Release Oil Hauler fell asleep while loading and overflowed his tank.	Date and Hour of Occurrence 10/31/14 - @ 0330 hrs	Date and Hour of Discovery 10/31/14 - @ 0700 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Not Required	If YES, To Whom? Tomas Oberding	
By Whom? B.J. Cox	Date and Hour 10/31/14 - 1200	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
During the loading of Oil for sales into a truck, the truck driver fell asleep, allowing his tanker to overflow. The driver has been permanently released from hauling oil from any GMT locations.

Describe Area Affected and Cleanup Action Taken.*
The majority of the spill was confined to the surface location between the well head and tank battery. There was some contamination just off of the constructed well pad. All contamination will be excavated until no further evidence of contamination is evident. Soil samples will then be taken from affected areas to confirm that all the contaminated soil has been removed. At that point, clean native soil will be brought in to replace what was removed, and the contaminated soil hauled to a proper disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: BJ Cox	Approved by Environmental Specialist: 	
Title: Production Superintendent	Approval Date: 11-3-14	Expiration Date: 1-5-14
E-mail Address: bjcox@gmtexploration.com	Conditions of Approval: <i>Site Supplies required detention & maintenance area per NMOCD guidance. Submit final C-141 by 1-3-14.</i>	Attached <input type="checkbox"/> IRP-3405
Date: 10/31/14 Phone: (307)-354-8895		

* Attach Additional Sheets If Necessary

09 11 260511
N70143072 8488
P701430 728674

NOV 04 2014