

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chevron USA Inc.	Contact: Edem Sededji
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No. 432-234-4437
Facility Name: VGSAU 110H	Facility Type: Oil Well

Surface Owner: N/A	Mineral Owner: State of New Mexico	API No. 30-025-36500
--------------------	------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 1	Township 18S	Range 34E	Feet from the 653	North/South Line SOUTH	Feet from the 20	East/West Line WEST	County LEA
------------------	--------------	-----------------	--------------	----------------------	---------------------------	---------------------	------------------------	---------------

Latitude 32.7714 Longitude -103.522

NATURE OF RELEASE

Type of Release: Spill to land	Volume of Release: 6.85 bbls	Volume Recovered
Source of Release: Stuffing box	Date and Hour of Occurrence: 10/17/2014 04:32 PM	Date and Hour of Discovery 10/17/2014 04:32 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

HOBBS OCD

NOV 3 1 2014

Describe Cause of Problem and Remedial Action Taken.*

RECEIVED

The spill was due to a stuffing box leak. Immediate remedial action was taken using a vacuum truck to clean up the spill.

Describe Area Affected and Cleanup Action Taken.*

The area affected was around the wellhead. The next step is for backhoe to excavate top layer of soil approximate 12" deep and soil samples will be taken to the laboratory to determine TPH, Benzene and Chlorides contaminants levels. In case any of the contaminants levels are still high, the spill location will be turned over to Chevron management Company (EMC) for further remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

 Invalid signature


X Edem Sededji

Edem Sededji
Environmental Specialist

Signature: Signed by: Edem Sededji

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:



NOV 04 2014

Printed Name: Edem Sededji			
Title: Health and Environmental Specialist		Approval Date: 10/31/14	Expiration Date: —
E-mail Address: etpo@chevron.com		Conditions of Approval: —	Attached <input type="checkbox"/> IRP 3407
Date: 10/29/2014	Phone: 432-234-4437		

* Attach Additional Sheets If Necessary

0974 4323
 11-01430 727085
 07014 30 727219

HOBBS OCD

OCT 31 2014

RECEIVED