

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

NOV 04 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

Name of Company Yates Petroleum Corporation		Contact Robert Asher
Address 104 S. 4 th Street		Telephone No. 575-748-4171
Facility Name Shocker SWD #1		Facility Type Battery
Surface Owner State	Mineral Owner State	API No. 30-015-39470

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	32	25S	29E	1400	North	990	East	Eddy

Latitude 32.09056 Longitude 104.00062

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 2 B/O & 75 B/PW	Volume Recovered 2 B/O & 75 B/PW
Source of Release Produced water tank	Date and Hour of Occurrence 9/27/2014; AM	Date and Hour of Discovery 9/28/2014; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 10/10/2014; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Fire at tank battery, caused by suspected lightning strike. Because of heavy rains and flooding, access was delayed. An approximate area of 30' X 100' (inside bermed and lined battery). All oil/produced water recovered (liner sustained no damage). All production equipment is being removed and replaced. Depth to Ground Water: >100' (approximately 120', per the ChevronTexaco Trend Map. Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0. Based on all oil /produced water recovered and battery is lined and liner intact, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: 11/5/14	Expiration Date: NA
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: November 4, 2014 Phone: 575-748-4217	2RP- 	

* Attach Additional Sheets If Necessary

2RP-2581

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Tuesday, November 04, 2014 9:37 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Form C-141, Initial & Final Report (Shocker SWD #1)
Attachments: Shocker SWD 1.pdf

Attached is the Initial/ Final C-141 requesting closure.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, September 19, 2014 3:28 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD
Cc: Amber Cannon; Chase Settle; Katie Parker; Manuel Gonzalez; Tanna Adams
Subject: Release Notification (Shocker SWD #1)

Yates Petroleum Corporation is reporting a release at the following location (9/19/2014; 11:00 AM).

Shocker SWD #1
30-015-39470
Section 32, T25S-R29E
1400 FNL & 990 FEL
Eddy County, New Mexico

Released: Unknown at this time; Recovered: Unknown at this time.

Cause of release was from a fire at the SWD battery, cause of fire is under investigation. Because of rains access was limited and YPC, Fire Department or vacuum trucks/roustabout crews are not on site as of yet. A Form C-141 with full detailed information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
