HORRES OCD

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 \(\)

State of New Mexico NOV Energy Minerals and Natural Resources

Oil Conservation Division RECEIVE 220 South St. Francis Dr.

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505													
Release Notification and Corrective Action													
						OPERATOR							
Name of Company Oxy Permian Ltd.							Chancey Summe						
Address 1017 W. Stanolind Rd, Hobbs, NM 88240						Telephone No. (575) 397-8216							
Facility Name South Mattix Battery						Facility Type Battery							
1 willy Italic South Matth Dation						racinty Type Dattery							
Surface Owner Grobey Mineral Owner							API No.						
LOCATION OF RELEASE													
Unit Letter									/West Line County				
	15	248	37E			İ		ĺ		Loo			
] 13	243	L					<u> </u>		Lea			
Latitude N 32.21709° Longitude W 103.14918°													
NATURE OF RELEASE													
Type of Rele				Volume of	Release 15 bb	ls	Volume I	Recovered	1 bbls				
Source of Release External corrosion on a 2" circulating line from the							Date and Hour of Occurrence			Date and Hour of Discovery			
circulating pump to the header Was Immediate Notice Given?						04/10/2014 If YES, To Whom?							
Was Infinediate Notice Given? ☐ Yes ☐ No ☐ Not Required													
By Whom? Jennifer Gilkey						Date and Hour 04/10/2014 @ 11:41 am							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
Yes 🛛 No							1 5						
If a Watercon	urse was Im	pacted, Descri	be Fully.*	*		_L							
If a Watercourse was Impacted, Describe Fully.*													
												i	
												ļ	
Describe Cause of Problem and Remedial Action Taken.*													
External corrosion on a 2" circulating line from the circulating pump to the header leaked 15 bbls of oil onto the ground. A vacuum truck recovered 1 bbls													
		paired or repla				- Around Tour	24 12 3310 01 00	oute inc	B-0			3,2200, 2,0000	
	·												
Describe Are	a Affected a	and Cleanup A	ction Tak	en.*									
The affected	area is annr	ovimately 40'	x 20' on 1	ocation Remedi	ation w	ill be complet	ed in accordance	with an	approved t	remediation	nlan fr	om NMOCD	
The affected area is approximately 40' x 20' on location. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.													
							knowledge and u						
							nd perform correc						
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
							on that pose a thre						
				tance of a C-141	report d	oes not reliev	e the operator of	responsi	bility for c	ompliance v	vith an	y other	
federal, state,	or local lav	ve and/or regu	lations.	\	Т		OH CON	a DDT	AFDIONI	TATE LIGHT	33.7		
						OIL CONSERVATION DIVISION							
Signature:													
						Approved by Environmental Specialist:							
Printed Name: Chancey Summers						Approved by	Environar S	pecialis	··				
CH. HEC	O "	_			\neq	A	46 .		Daniel	Date	• •		
Title: HES	Coordinato	ľ				Approval Dat	C://~/Ø -/9		Expiration	Date: /-	10-15		
E-mail Addre	ess: Chan	cey_Summers	n		Conditions of	Approval:			A ++11				
(1 15.111						Soto Syle rognest Bolinto Ember air ay Norse goods - Solar film Coffe oy 1-10-19			Attached				
Date: 7	15-17	, ICNI	Phone:	(575) 397-821	6	security &	melate as	nap	en_	IKP	1418		
Attach Additional Sheets If Necessary Necessary								the					
						Cr/41 0y	1-10-17			170 14	3149	190 48	