

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact Kenny Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-8545
Facility Name Rio Blanco 4 Fed 3 SWD	Facility Type SWD

Surface Owner	Mineral Owner	API No. 30-025-36425
---------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	4	23S	34E	1650	SOUTH	1650	EAST	LEA

Latitude: ___ Longitude: ___

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 65bbls	Volume Recovered 65bbls
Source of Release Charge pump pipe	Date and Hour of Occurrence 5/30/14	Date and Hour of Discovery 5/30/14 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kenny Kidd-Foreman/ Garry Michael-Assistant Foreman/ Scott Poe-EHS/Jerry Mathews-Superintendent/Hobbs OCD-Geoffery Leking/BLM-Jeff Robertson	
By Whom? Matt Nettles	Date and Hour 5/30/14 11:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The needle valve came out of the pipe which is connected to the charge pump. This caused 65 barrels of produced water to be released. 60 barrels in the containment and 5 bbls outside of the containment. The well was shut off. A vacuum truck was immediately called for vacuum services. 65 barrels of produced water was recovered. The pump was repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected was within the burm approximately 30 feet wide by 60 feet long. The affected area outside the containment was approximately 5 feet wide by 75 feet long. Talon LPE was contacted to perform the site assessment and soil sampling activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Shammy Ingram</i>	OIL CONSERVATION DIVISION	
Printed Name: Shammy Ingram	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 12-11-14	Expiration Date: 2-11-15
E-mail Address: Shammy.Ingram@dvn.com	Conditions of Approval: <i>Site specific report Revised procedure re report NMOCD guidance. Submit final C-141 by 2-11-15.</i>	Attached <input type="checkbox"/> IRP-3450
Date: May 30, 2014	Phone: 575-748-0174	

* Attach Additional Sheets If Necessary

DEC 1 2 2014

6177
N70143454 4342
P70143454 4863