

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

*F-AB1435830421* **Release Notification and Corrective Action**

*MAB1435832053* OPERATOR  Initial Report  Final Report

Name of Company OXY USA WTP LP <i>193029</i>	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21-S	23-E					Eddy

Latitude 32°27'52.502" Longitude 104°34'28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 80.62 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 6/10/2014 3:10:00 PM	Date and Hour of Discovery 6/10/2014 3:10:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

JUL 16 2014

RECEIVED

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Cause:  
OXY INDIAN BASIN GAS PLANT FLARED 80.62 MCF OF SWEET INLET GAS DUE TO HIGH PRESSURE OF LINE FROM ENTERPRISE PUTTING LINE 5B INTO SERVICE. PRESSURE CONTROL VALVE OPENED UP TO PREVENT LINE FROM OVERPRESSURE.  
Remedial Action Taken:  
OPERATIONS STARTED ADDITIONAL COMPRESSORS TO HANDLE INCREASED PRESSURE.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor:	
Title: <i>HEJ Specialist</i>	Approval Date: <i>12/23/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: <i>7-14-14</i>	Phone: 575-628-4167	

\* Attach Additional Sheets If Necessary

*269-2691*