

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

PAB1435830421

Release Notification and Corrective Action

LAB 1436538942

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 22105.3 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 6/26/2014 3:42:00 AM	Date and Hour of Discovery 6/26/2014 3:42:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 06.27.2014 10:11 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

NM OIL CONSERVATION

If a Watercourse was Impacted, Describe Fully.\*  
N/A

ARTESIA DISTRICT

JUL 16 2014

Describe Cause of Problem and Remedial Action Taken.\*

RECEIVED

Cause:  
OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 396 MINUTES DUE TO HIGH OXYGEN CONTENT.

Remedial Action Taken:  
SOURCE OF OXYGEN WAS DETERMINED TO BE ENTERING THE PLANT ON LINE 5. ENTERPRISE WAS NOTIFIED AND STARTED TO SAMPLE TO DETERMINE EXACT SOURCE. LINE 5 WAS SHUT IN. ONCE SOURCE OF OXYGEN WAS DETERMINED, AND BLOCKED IN, LINE 5 WAS OPENED BACK UP TO THE INLET OF THE PLANT. OXY FLARED SEVERAL MORE TIMES TILL LINE 5 WAS CLEAN.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Rodney Campbell

Printed Name: RODNEY CAMPBELL

Approved by District Supervisor Mike Bratcher

Title: HES Specialist

Approval Date: 12/31/14

Expiration Date: N/A

E-mail Address: RODNEY\_CAMPBELL@OXY.COM

Conditions of Approval:

FINAL

Attached ☐

Date: 7-14-14

Phone: 575-628-4167

\* Attach Additional Sheets If Necessary

PAB1436539441

2RP-2699