

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

fAB1435830421

Release Notification and Corrective Action

NAB1436458140

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP	193029	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

~~32.589444~~ ~~104.566666~~
Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE



Type of Release Gas	Volume of Release 263.4 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 6/19/2014 8:43:00 AM	Date and Hour of Discovery 6/19/2014 8:43:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

NM OIL CONSERVATION

If a Watercourse was Impacted, Describe Fully.* N/A	ARTESIA DISTRICT JUL 16 2014
--	---------------------------------

Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 4 MINUTES DUE TO HIGH OXYGEN CONTENT. Remedial Action Taken: OPERATIONS STARTED TO CHECK INLET LINES, BUT DIDN'T FIND SOURCE OF OXYGEN.	RECEIVED
Describe Area Affected and Cleanup Action Taken.* N/A	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor:  Signed By	
Title: HES Specialist	Approval Date: 12/30/14	Expiration Date: N/A
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 7-14-14	Phone: 575-628-4167	

* Attach Additional Sheets If Necessary

27P-2698