District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 875

HOBBS OF State of New Mexico
Energy Minerals and Natural Resources
JAN 0 5 Oil Conservation Division

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				1220 South St. Francis Dr. RECEIVED Santa Fe, NM 87505					ac	cordance wi	th 19.1	5.29 NMAC.
		·	Rele	ease Notific	atio	n and Co	orrective A	ction	1			
<u> </u>		OPERATOR										
Name of Company SM Energy							Contact Tejay Simpson					
Address 6301 Holiday Hill Road, Midland, TX 79707							Telephone No. 432-212-3408					
Facility Nar	ne Inca B	Facility Type Production Battery										
Surface Owner BLM Mineral Owner								API No. 3002530039 (closest well)			losest well)	
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/\	West Line	County		
	19	18S	32E	760	North		330	West		LEA		
]	Latitude_32.73	805_ L	ongitude	-103.81254	_				
NATURE OF RELEASE												
Type of Release Produced Water Spill						Volume of Release 75			Volume Recovered 70			
Source of Re	lease Wate	Date and Hour of Occurrence			Date and Hour of Discovery							
		12/21/14										
Was Immediate Notice Given? ☐ Yes ☒ No ☐ Not Required						If YES, To	Whom?					
By Whom?						Date and Hour						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercou	irse was Im	pacted, Descr	ibe Fully.*	* NA								
ì												

Describe Cause of Problem and Remedial Action Taken.*

The tank battery PLC malfunctioned resulting in the produced water tank level control to the water transfer pump and the call out high level alarm not working properly and not making call out notification to the lease operator. Upon arrival to the battery during routine rounds the lease operator found the produced water tank over flowing out of the tank hatch. The produced water was contained within the tank berm with the exception of approximately 1 barrel of water that over ran the top of the berm. Spill volume estimated at 75 barrels of produced water and 1 barrel of oil. Total fluid recovered is estimated at 70 barrels of water and 0.75 barrels of oil. Back hoe and contract gang was dispatched to the site and began removal of contaminated soil with disposal scheduled at CRI. Electrician and PLC programmer were dispatched to the facility to make the repair to the PLC.

Describe Area Affected and Cleanup Action Taken.*

Tank battery pad inside of the tank berm with a small area north of the berm on the access road way. Free standing fluid was recovered. Contaminated soil was excavated and disposal scheduled at CRI.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

federal, state, or local laws and/or regulations	S						
		OIL CONSERVATION DIVISION					
Signature:		- /n					
Printed Name: Tejay Simpson	Approved by Environmental Specialist:						
Title: District Production Superintendent	Approval Date: (-5-/s	Expiration [ration Date: 3-5-/s				
E-mail Address: tsimpson@sm-energy.com	Conditions of Approval: Let Sylan agad. Del Le machine may be OCP	Attached	,				
Date: 12/23/14	Phone: 432-212-3408	Exercises men for OCP	IRP-3475				
	- A 483				13440		

JAN 08 2015

shot ful 6-19/ by 3-5-15.

nto 150055648