

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Minerals and Natural Resources
Oil Conservation Division
220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact Kenny Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-8545
Facility Name Rio Blanco 4 Fed 3 SWD	Facility Type SWD

Surface Owner	Mineral Owner	API No. 30-025-36425
---------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter J	Section 4	Township 23S	Range 34E	Feet from the 1650	North/South Line SOUTH	Feet from the 1650	East/West Line EAST	County LEA
-------------------------	---------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude: _____ Longitude: _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 1560 BBLS	Volume Recovered 30 BBLS
Source of Release The collar around an 8" fiberglass water line had	Date and Hour of Occurrence 8/13/14 4:00 PM	Date and Hour of Discovery 8/14/14 4:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kenny Kidd-Foreman/Jerry Mathews-Superintendent/Hobbs OCD-left message/BLM-Jeff Robertson	
By Whom? Matt Nettles	Date and Hour 8/14/14 4:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The collar around an 8" fiberglass water line separated causing an estimated 1560 bbls of produced water to be released.

Describe Area Affected and Cleanup Action Taken.*
The lease operator discovered the leak causing an estimated 1560 bbls of produced water to be released outside of location and onto pasture, the north side of the north west corner. Approximately 30 bbls of produced water was recovered. The well was shut in and all lines coming to the SWD were shut off. All necessary parties were notified. The water line was repaired.

The impacted area was excavated to a depth of 4 feet deep and a 20 mil liner was installed. The contaminate soil was transported to Lea Land LLC, an approved disposal facility.

The excavated area was backfilled with clean sand that was obtained by the owner and placed on top of the liner. The area was contoured to match the surrounding location and seeded with BLM #2 seed mix for sand soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 1-13-15	Expiration Date: _____
E-mail Address: corina.moya@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: January 13, 2015 Phone: 575-746-5559		IRP-3208

* Attach Additional Sheets If Necessary

JAN 15 2015