

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 16 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1501655607

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	RKI E&P, LLC	Contact	Zack Laird
Address	210 Park Ave. - Ste. 900, OKC, OK 73102	Telephone No.	405-742-2696
Facility Name:	Brushy Creek Gathering Station	Facility Type :	Tank Battery

Surface Owner	Federal	Mineral Owner	NA	API No.	30-015-24451
---------------	---------	---------------	----	---------	--------------

LOCATION OF RELEASE

(UCBH WW Fed. #3)

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	26S	29E		660 FSL		1980FWL	Eddy

Latitude: 32.007240348386 Longitude: -103.940095327473

NATURE OF RELEASE

Type of Release. Produced Water/Oil	Volume of Release: 10oil/40water Bbls	Volume Recovered: 8oil/35water Bbls
Source of Release Tanks overran due to pump salt-off	Date and Hour of Occurrence 01/07/15 - prior to 0800hrs MT	Date and Hour of Discovery 01/07/15 - 0800hrs MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*



The transfer pump, which moves fluids from gathering battery to SWD well, salted off and tanks ran over. All fluids contained in secondary containment berm.

Wells producing to gathering battery were shut-in, vac trucks recovered free fluid and pump repairs were made. Plan to install high-level alarms/shutdowns on battery.

Describe Area Affected and Cleanup Action Taken.*

All fluid remained in secondary containment berm, 43/50Bbls spilled were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Zack Laird		Approved by Environmental Specialist: 	
Title: Sr. EHS Manager		Approval Date: 1/16/15	Expiration Date: NA
E-mail Address: ZLaird@rkixp.com		Conditions of Approval:	
Date: 01/15/15 Phone: 405-987-2213		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

ATER THAN: 2/16/15

2RP-2742

Patterson, Heather, EMNRD

From: Zackary Laird <ZLaird@rkixp.com>
Sent: Friday, January 16, 2015 9:05 AM
To: Patterson, Heather, EMNRD
Cc: Hughes, Solomon
Subject: RKI E&P Spill Notification and C-141
Attachments: NM_BrushyCreekGatheringStation_InitialC141(011515).pdf

Heather,

Attached please find completed OCD form C-141 for a spill occurring at the RKI operated Brushy Creek Gathering Station in Eddy County, NM. I used the legals for the RKI operated UCBH WW Federal 003 (API # 30-015-24451) as it is on the same pad as the gathering battery. I apologize for the delayed report.

Please feel free to contact myself or a local RKI representative with any questions.

Kind Regards,

Zack Laird | Sr. EHS Manager

RKI Exploration & Production, LLC

210 Park Avenue, Suite 900 | Oklahoma City, OK 73102

405.987.2213 (o) | 405.742.2696 (m) | ZLaird@rkixp.com

This email is confidential. If you believe it has been sent to you in error, then do not read it, do notify the sender you have received it, and delete it. Email transmissions cannot be warranted to be secure or error-free as information could be intercepted, misdirected, corrupted, lost, incomplete, destroyed or containing viruses. The sender therefore cannot guarantee the integrity or security of this email or any file(s) included herewith. RKI and the sender hereby disclaim any and all liability for injury or damages that may result from the recipient(s) receipt or transmission of this email and any file(s) included herewith or reliance on the contents thereof. Any oilfield equipment, materials or services ordered by or provided to RKI or its affiliates in connection with this message shall be governed by RKI's Terms and Conditions of Purchase (a copy of which may be found at www.rkixp.com) and such Terms and Conditions of Purchase are hereby incorporated and expressly made a part hereof. A paper copy of RKI's Terms and Conditions of Purchase will be provided upon your written request.