District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

	Santa Pe, NW 87505											
Release Notification and Corrective Action												
1						OPERA'	ГOR	☐ Initi	☐ Initial Report ☐ Final Report			
		arvey E. Ya				Contact- Tammy R. Link						
		933, Roswel		201-1933		Telephone No. 575-623-6601						
Facility Na	me – Amo	co 1 Federal	#1			Facility Type – API #30-025-28889						
Surface Ow	ner - Fee			Mineral (Owner	API No. 30-025-28889						
1	<u></u>									J		
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County												
K	Section	18S	Range 32E	1980'	Norti	1/South Line S	1980'	East/West Line W	County	Lea		
Latitude Longitude												
NATURE OF RELEASE												
Type of Rele	ase - 57 b	ols total fluid		INAI	UKE	Volume of Release – 57 bbls Volume Recovered 35 bbls						
Type of Release – 57 bbls total fluid Source of Release							lour of Occurrence		Date and Hour of Discovery-1/5/15 7:15			
Fire tube gasket blew and caused release						1/4/15 after 5:00 pm am						
Was Immediate Notice Given?							If YES, To Whom? Tomas Oberding					
Yes No Not Required Bill with OCD in Hobbs												
By Whom? Keith Cannon Was a Watercourse Reached?						Date and Hour 1/5/15 at 10:45 am If YES, Volume Impacting the Watercourse.						
was a water	course Reac		Yes 🗵	l No		II YES, VO					1	
If a Watercourse was Impacted, Describe Fully.*												
In In												
Wall by a second of the second												
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Fire tube gasket blew Describe Area Affected and Cleanup Action Taken.*												
	Describe Cause of Problem and Remedial Action Taken.* Fire tube gasket blew											
I no taot gao							EIVE)·				
		and Cleanup A	Action Tal	en.*			~	,				
Replace fire	tube gasket	and r and encay w	ith overen	ray in pactura w/1	ነበበበ ሰዓ	ls of water 3%	microblaze Ren	nediation complete	ed and soil se	ımnles s	re attached	
Sicalii Cicali I	icator ireate	and spray w	iii oveisp	tay in pasture wr	iooo ga	ns of water 57	moroonaze. Rei	nediation complete	a ana son se	inpios c	no anaonea.	
I hereby cert	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
		vs and/or regu								***************************************		
						OIL CONSERVATION DIVISION						
Signature: Our W- Lile												
						Approved by Environmental Specialist:						
Printed Name:Tammy R. Link						Hydelyist						
Title: Engine	ering Took					Annroval Da	te: <i>1-21-15</i>	Expiration	Date: \			
Title. Engine	oring reell	<u>, </u>				Approvai Da	··· · · · · / / / / /	Daphation			······································	
E-mail Addre	ess: tlink@h	eycoenergy.c	om			Conditions o	f Approval:		Attached			
Date: 1/1	19/15	·	Dhono	·575-623-6601		~			IR P-3486			