

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 12 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	RKIE&P, LLC	Contact	Zack Laird
Address	210 Park Ave. - Ste. 900, OKC, OK 73102	Telephone No.	405-742-2696
Facility Name:	RDX 17-14	Facility Type :	Oil and Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-39845
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	30E		990 FSL		1650FWL	Eddy

Latitude: 32.0379455094502 Longitude: -103.906704631448

NATURE OF RELEASE

Type of Release. Produced Water	Volume of Release: 30Bbbs	Volume Recovered: 30Bbbs
Source of Release Tanks over ran because tank level sensor failed to work properly.	Date and Hour of Occurrence 02/12/15 - 0730hrs MT	Date and Hour of Discovery 02/12/15 - 0830hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson (left VM on office line)	
By Whom? Zack Laird	Date and Hour: 02/12/15 - 1530hrs CT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A



Describe Cause of Problem and Remedial Action Taken.*

Water tanks over ran because tank level gauge/switch failed to function and activate transfer pump, so fluid transfer did not occur.
Turned transfer pump on, repaired switch, recovered fluid with vac truck and will wash lined secondary containment.

Describe Area Affected and Cleanup Action Taken.*

All fluid remained in secondary containment berm, 30/30Bbbs recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Zack Laird		Approved by Environmental Specialist: 	
Title: Sr. EHS Manager		Approval Date: 2/17/15	Expiration Date: N/A
E-mail Address: ZLaird@rkixp.com		Conditions of Approval:	
Date: 02/12/15 Phone: 405-987-2213		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 3/17/15	

* Attach Additional Sheets If Necessary

2RP-2813

Patterson, Heather, EMNRD

From: Taylor Jones <TJones@rkixp.com>
Sent: Thursday, February 12, 2015 2:49 PM
To: 'Heather.Patterson@state.nm.us'
Cc: shughes@blm.gov; Zackary Laird
Subject: RKI E&P Spill Notification and C-141
Attachments: NM_Ross Draw14_InitialC141(021215)-signed.pdf; NM_RDX17-14_InitialC141(021215).pdf; NM_NBD35-4H_InitialC141(021215).pdf

Heather,

Attached please find completed OCD forms C-141 for spills occurring at three RKI wells: Ross Draw #14, RDX 17-14, and North Bushy Draw 35-4H in Eddy County. Zack Left you a voicemail regarding the spills on the RDX 17-14 and North Bushy Draw 35-4H.

Please feel free to contact myself or a local RKI representative with any questions.

Thank you,

Taylor Jones

RKI Exploration & Production, LLC

210 Park Avenue, Suite 900

Oklahoma City, OK 73102

405-996-5782 (o) | 405.326.0791 (m)

TJones@RKIXP.com

This email is confidential. If you believe it has been sent to you in error, then do not read it, do notify the sender you have received it, and delete it. Email transmissions cannot be warranted to be secure or error-free as information could be intercepted, misdirected, corrupted, lost, incomplete, destroyed or containing viruses. The sender therefore cannot guarantee the integrity or security of this email or any file(s) included herewith. RKI and the sender hereby disclaim any and all liability for injury or damages that may result from the recipient(s) receipt or transmission of this email and any file(s) included herewith or reliance on the contents thereof. Any oilfield equipment, materials or services ordered by or provided to RKI or its affiliates in connection with this message shall be governed by RKI's Terms and Conditions of Purchase (a copy of which may be found at www.rkixp.com) and such Terms and Conditions of Purchase are hereby incorporated and expressly made a part hereof. A paper copy of RKI's Terms and Conditions of Purchase will be provided upon your written request.