

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 24 2015

Submit a Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1505630079

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471
Facility Name Antweil ANU Federal #4-H	Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-40426
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter M	Section 29	Township 19S	Range 30E	Feet from the 860	North/South Line South	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.62641 Longitude 104.0001

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 30 B/O	Volume Recovered 29 B/O
Source of Release Heater Treater	Date and Hour of Occurrence 2/17/2015; AM	Date and Hour of Discovery 2/17/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 2/18/2015; AM (Email) → 2/17/15 10:35 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The back pressure valve on the heater treater failed, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 40' x 120' within the lined and bermed battery, and approximate area of 40' x 40' outside of the battery. The back pressure valve was replaced after a vacuum truck recovered most of the released crude oil (29 B/O). Impacted gravel will be hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX. If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: 50-99' (approximately 90', Section 29, T19S-R30E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: 2/25/15	Expiration Date: N/A
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	
Date: February 24, 2015	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 3/25/15	

* Attach Additional Sheets If Necessary

Attached ☐

2RP-2835

Patterson, Heather, EMNRD

From: Tanna Adams <TCArms@yatespetroleum.com>
Sent: Tuesday, February 24, 2015 8:54 AM
To: Bratcher, Mike, EMNRD
Cc: Bob Asher; Patterson, Heather, EMNRD; jamos@blm.gov
Subject: Antweil ANU Federal #4-H
Attachments: Antweil ANU Federal #4H_C141Initial_021715.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial for the below listed location:

**Antweil ANU Federal #4-H
30-015-40426
Section 29, T19S-R30E
860 FSL & 660 FWL
Eddy County, New Mexico**

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Tech

Environmental Department

TCArms@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Tuesday, February 17, 2015 10:35 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov
Cc: Amber Cannon; Chase Settle; Katie Parker; Tanna Adams
Subject: Release Notification (Antweil ANU Federal #4-H)

Yates Petroleum Corporation is reporting a release at the following location (2/17/2015, 6:30 AM).

Antweil ANU Federal #4-H
30-015-40426
860 FSL & 660 FWL
Section 29, T19S-R30E
Eddy County, New Mexico

Released: 30 B/O; Recovered: In Process.

Cause of the release is valve failure on a heater, the release was contained within a lined/bermed battery. A Form C-141 with complete information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
