


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Linn Operating	Contact Gary Wink
Address 2130 W. Bender Blvd. Hobbs, NM 88240	Telephone No. (575) 738-1739
Facility Name J.L. Keel B #072	Facility Type Injection
Surface Owner BLM	Mineral Owner BLM
Lease No. 3001528580	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	5	17S	31E	2230'	FSL	760'	FEL	Eddy

Latitude 32.86242 Longitude -103.88504

NATURE OF RELEASE

Type of Release Produced Water/Oil	Volume of Release 35 bbls/5 bbls	Volume Recovered 0/0
Source of Release 2" Fiberglass HP line	Date and Hour of Occurrence 1/8/2013 9:30 am	Date and Hour of Discovery 1/9/2013 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD; Terry Gregston, BLM	
By Whom? Jose Hernandez	Date and Hour 1/9/13 9:45 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* On 1/8/13 at 2130 Linn received an alarm at the Keel West for header discharge pressure. The line was shut in but the leak could not be located in the dark. The leak was found on 1/9/13 at 0900 hrs. The leak was caused by a failure in line at 2" collar. A total of 5,576 sq ft of road and pasture were affected.

Describe Area Affected and Cleanup Action Taken.*

On January 9th, 2013, RECS personnel were on site to initialize work on the J.L. Keel B #72. Soil samples were taken from the surface of the release (Figure 1) and the samples were taken to a commercial laboratory for analysis of chlorides, GRO and DRO. Based on the sampling data, Linn submitted a Corrective Action Plan (CAP) on March 8th, 2013. BLM approved this CAP on March 11th, 2013 with the following conditions:

1. Confirmatory samples of the bottom and sidewalls would need to be taken of the pasture area;
2. The site should be backfilled with native soils matching the surrounding terrain, re-contoured, and seeded using the LPC seed mix.

Site excavation began on March 20th, 2013. The lease road was scraped down six inches. The release areas in the north pasture was excavated down four feet and the release areas in the south pasture were excavated down six inches and two feet (Figure 2). A total of 384 yards of soil was taken to a NMOCD approved facility for disposal. Representative samples from the pasture areas were taken to a commercial laboratory for analysis of chlorides, TPH and BTEX. A surface sample was taken at Pt. 6 and taken to a commercial laboratory for analysis of chlorides, TPH and BTEX. The laboratory chloride reading returned a result of 96 mg/kg and TPH and BTEX readings of non-detect. BLM verbally approved the backfilling of the site and the site was backfilled with clean, imported soil. A total of 396 yards of caliche and top soil was imported to the site to serve as backfill. A sample of the imported soil was taken to a commercial laboratory for analysis of chlorides and returned a result of non-detect. The site was backfilled and contoured to the surrounding location. The site was backfilled, was contoured to the surrounding location, and was seeded on July 16th, 2013 with LPC seed mix.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary W. Wink</i>	OIL CONSERVATION DIVISION	
Printed Name: Gary Wink	Approved by District Supervisor: <i>[Signature]</i>	
Title: Production Foreman	Approval Date: <i>10/6/14</i>	Expiration Date: <i>NA</i>
E-mail Address: gawink@linenergy.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: <i>7/19/13</i>	Phone: (575) 738-1739	

* Attach Additional Sheets If Necessary

2RD-1585