District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec. NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

いたで

語

1. A. S. S.

が読

LANG.

STATE OF

時間に山

語いない

1. Chill Fel

0.45400

WORLD IN

RECEIVED State of New Mexico Energy Minerals and Natural Resources 3 2014

Form C-141 Revised August 8, 2011

API No. 3001505117

Oil Conservation Division OF ARTSOMIAL Copy to appropriate District Office in accordance with 19.15.29 NMAC accordance with 19.15.29 NMAC. 1220 South St. Francis Dr.

Santa Fe, NM 87505

Release Notification and Corrective Action

	OPERATOR	Initial Report	Final Report
Name of Company Linn Operating	Contact Brian Wall		
Address 2130 W. Bender, Hobbs, NM 88240	Telephone No. (806) 367-0645		
Facility Name HE West B 10	Facility Type Injection		
	· · · · · · · · · · · · · · · · · · ·		

Surface C)wner	Federal	

LOCATION OF RELEASE									
	Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
				-					-
	Е	09	175	31E	1980	North	660	West	Eddy

Mineral Owner

Latitude_32.85087___ Longitude_-103.88039_

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20 bbls	Volume Recovered 0
Source of Release Fiberglass pipeline	Date and Hour of Occurrence	Date and Hour of Discovery 10/14/2013
	10/14/2013 12:00pm	12:00pm
Was Immediate Notice Given?	If YES, To Whom?	
Yes 🗌 No 🗌 Not Required	Mike Burton – BLM Mike Bratche	er - NMOCD
By Whom? Brian Wall	Date and Hour 10/16/2013 7:15a	um
Was a Watercourse Reached?	If YES, Volume Impacting the Wate	ercourse.
🗌 Yes 🖾 No		
If a Watercourse was Impacted Describe Fully *	I	

Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.* Found location of injection line leak which had put injection out of service in area. Spill composed of fresh and produced water. Approx 20 barrels total fluid. Were using pump truck with fresh water at time to find location of leak. Describe Area Affected and Cleanup Action Taken.* The release affected 1,841 sq ft of pasture land. RECS was on site beginning October 17th, 2013 to

assess the site. Three points were sampled at the surface and two of the points were sampled with depth. The samples were field tested for chlorides and for organic vapors using a PID meter. Representative samples were taken to a commercial laboratory for analysis. On November 18th, 2013, a Corrective Action Plan (CAP) was submitted to NMOCD and BLM. BLM approved the CAP on November 18th, 2013 and NMOCD approved the CAP on November 19th, 2013. CAP work began at the site on January 8th, 2014. The site was line spotted by hydrovac to prevent line strikes and the lines were padded with soil to prevent breakage. The site was excavated as proposed in the CAP. A total of 240 yards of contaminated soil was taken to a NMOCD approved facility for disposal. Once the 4 ft and 2.5 ft excavations were completed, final wall sampling of both excavations was conducted and the samples delivered to a commercial laboratory. A 5 point bottom composite of the 2.5 ft excavation was taken to a commercial laboratory. At the base of the 4 ft excavation, a 20-mil reinforced poly liner was installed and properly seated into the base of the excavation. The liner was padded with 6 inches of top soil to protect the liner from punctures. Then a total of 44 yards of caliche was placed over the padded liner. The remainder of the 4 ft excavation, the 2.5 ft excavation and the scrape was then backfilled with top soil. A total of 296 yards of top soil was imported to the site to pad the liner and serve as backfill. A 5 point composite sample of the imported soil was taken to a commercial laboratory for analysis and returned a chloride value of non-detect. On February 5th, 2014, soil amendments were added to the soil and the site was seeded with BLM mix #4.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

	OIL CONSERVATION DIVISION
Signature: Fred B Wall	
Printed Name: Brian Wall	Approved by Environmental Specialist:
Title: Construction Foreman II	Approval Date: 3/20/15 Expiration Date: N/A
E-mail Address: bwall@linnenergy.com	Conditions of Approval:
Date: 3/7/14 Phone: (806) 367-0645	tina -
* Attach Additional Sheets If Necessary	2RP-1995