

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAY 30 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|-----------------|--------------------------------------|---------------|-------------------|
| Name of Company | Oxy Permian Ltd. | Contact | Christopher Jones |
| Address | 1502 W. Commerce Drive, Carlsbad, NM | Telephone No. | (575) 628-4121 |
| Facility Name | Winston Gas Com Btry | Facility Type | Gathering |
| Surface Owner | BLM | Mineral Owner | |
| | | Lease No. | NM LC 063246 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|-----------------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| B | 31 | 21S | 24E | | | | | Eddy County, NM |

Latitude N 32.441

Longitude W 104.536

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|---|----------------------------|----------|
| Type of Release | Oil and Produced Water | Volume of Release | 700 bbls | Volume Recovered | 650 bbls |
| Source of Release | Gasket failure on free water knockout | Date and Hour of Occurrence | 08/10/2012 @ 8:00 am | Date and Hour of Discovery | |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Mike Bratcher-NMOCD; Terry Gregston-BLM | | |
| By Whom? | Chris Jones | Date and Hour | 08/14/2012 @ 10:08 am | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gasket failure on the free water knockout caused 700 bbls of oil and produced water to leak onto the ground. 650 bbls of liquid were recovered via vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 60' x 150'. 650 bbls of oil and produced water were recovered. Additional remediation was completed as described in the remediation plan approved by Mike Bratcher of NMOCD via email on 01/24/2013 and also approved by Terry Gregston of the BLM via email on 01/30/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Christopher Jones

Title: HES Specialist

E-mail Address: Christopher.Jones@oxy.com

Date: 5/29/13

Phone: (575) 328-4121

Approved by District Supervisor:

Approval Date: 4/21/15

Expiration Date: N/A

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

22P-1281