<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

DEC 1 9 2012 Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate

NMOCD ARTES CALIFORNIA Rule 116 on back side of form

Release Notification and Corrective Action	Release	Notification	and Correct	ctive Action
--	---------	--------------	-------------	--------------

MLB12	35457	560				OPERA'	ГOR		X Initi	al Report	Final Rep
Name of Company Oxy Permian Ltd. 16696							J Summers			~	
ddress 1017 W. Stanolind Rd, Hobbs, NM acility Name Federal 12-1 South Battery						Telephone No. (575) 397-8216					
cility Nan	ne Feder	al 12-1 Sout	th Battery	·		Facility Typ	e Gathering				
Surface Owner BLM Mineral Owner					wner	Lease No. 30-015-26742					-26742
				TOCA	TION	OF RE	TEASE	<u></u>			
nit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/We	est Line	County	
			•								
M	12	228	31E				<u> </u>	<u> </u>		Eddy	
			3	Latitude		Longit	ude				
				NAT	HRE	OF REL	FASE				
pe of Rele	ase Oil a	nd produced v	water	NA.	OKL		Release 3 bbls	of oil	Volume l	Recovered	80 bbls
· · · · · · · · · · · · · · · · · · ·					and 100 bbls of produced water						
urce of Re	lease Pun	np failure				Date and Hour of Occurrence Date and Hour of Discovery					scovery
as Immedia	ate Notice (Given?				If YES, To					
			Yes 🗆	No 🗌 Not Re	quired		cher-OCD; James	Amos-Bl	LM		
Whom?	Dusty Wi	Isori				Date and I	Hour 11/03/201	1 @ 1.12	nm		
	course Read	ched?		·		Date and Hour 11/03/2011 @ 1:13 pm If YES, Volume Impacting the Watercourse.					
]Yes 🛚] No							
a Watercou	irse was Im	pacted, Descr	ibe Fully.	ķ		.L,					
		_	-								
									*		
							*				
scribe Cau	ise of Probl	em and Reme	dial Action	n Taken.*	-		i				
		bls of oil and	100 bbls o	of produced water	to leak	onto the grou	ind. A vacuum tr	uck recov	ered the i	remaining fl	uids, 80 bbls total
e pump wa	as repaired.			-							
scribe Are	a Affected	and Cleanup	Action Tak	en.*							
	cted is appi ed remediai		0' x 50'. A	A vacuum truck re	covered	180 bbls and	further remediation	on will be	conducte	ed in accorda	ance with OCD ar
ли арргоч	ca remodia	Ton plans.									
ereby certi	fy that the	information g	iven above	is true and compl	ete to tl	he best of my	knowledge and u	inderstand	I that pur	suant to NM	OCD rules and
gulations al	ll operators	are required t	to report as	nd/or file certain re	elease n	otifications a	nd perform correc	ctive actio	ns for rel	leases which	may endanger
ould their o	or the envi	ronment. The lave failed to	acceptant adenuately	ce of a C-141 repo investigate and re	rr by the emediate	e contaminat	ion that nose a thr	eport do	es not rea	neve ine ope er surface w	rator of hability ater, human healtl
the environ	nment. In a	ddition, NMO	OCD accep	tance of a C-141	report d	oes not relie	e the operator of	responsib	ility for o	compliance v	with any other
ieral, state,	or local la	ns aud or tea	ulations.			· · · · · · · · · · · · · · · · · · ·					
			_				OIL CON	SERV	ATION	DIVISIO	<u> </u>
gnature:		_		.)			,	ヘルド		and a section	
						Approved by	Distigned By	1011/4	12/12/	MONGE C	
inted Name	e: Chance	ey Summers						046			
tle: HES	Specialist					Approval Da	DEC 19 2	$2012 _{E}$	xpiration	Date:	
			_								
mail Addre	ess: Chan	cey.Summers	@oxy.con	<u> </u>		Conditions o	f Approval:			Attached	
ate: /	2-18-	12	Pho	one: (575) 397-821	į.			s autoc	&		
		ets If Necess		(5.5) 551 521		Remedi	ation per OCI	J Kules	∪Ni ⊶	701	WINI
		•	•		G		CLIRMIT KEW	יירועשו	∪ 14	d/4P	- 1404
										•	, ,
					ارج	0.00	submitted &	APPINA	ed		
					۲c	040201=	· ·	, .			

Bratcher, Mike, EMNRD

From:

Dusty Wilson@oxy.com

Sent:

Thursday, November 03, 2011 1:13 PM

To:

Bratcher, Mike, EMNRD; jamos@blm.gov

Cc:

cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

Chancey Summers@oxy.com; Leslie Moreno@oxy.com

Subject:

Federal 12-1 South Battery

Gentlemen, this email is to initially report that OXY had a Reportable spill at the Federal 12-1 South Battery yesterday, Sec 12 T22s R31e Eddy Co. This was due to a pump failure at the location. It caused the tanks to over fill and spill 3 bbls of oil and 100 bbls of produce water into the surrounding dyke. A vac truck was dispatched and recovered all remaining fluids from the surface soils, 80 bbls total. This site will be remediated to NMOCD and BLM guidelines. A C-141 is to follow. If you have any questions please feel free to contact me. Thanks.

Thanks,

Dusty L. Wilson HES Specialist Seminole, Lea County RMT.

"You will never succeed, if not given the chance to fail."