

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 1 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

AB1433736499

Release Notification and Corrective Action

AB1515336109

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Enterprise Field Services LLC/1000347	Contact Dina Ferguson
Address PO Box 4324, Houston TX 77210	Telephone No. 210-528-3824
Facility Name Pipeline ROW, 1002 Gathering Lateral	Facility Type Gas Gathering Pipeline
Surface Owner Private Owner	Mineral Owner NA - Pipeline
API No. NA	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	35	24S	28E	409	South	413	East	Eddy

Latitude N 32.174988 Longitude W -104.050735

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 1394 MCF	Volume Recovered NA
Source of Release Pipeline Release	Date and Hour of Occurrence 5/22/2015 @ 8:00 MDT	Date and Hour of Discovery 5/22/2015 @ 10:30 MDT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD District 2	
By Whom? Osman De Leon	Date and Hour 5/22/2015 @ 11:22 MDT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Line 1002 pressure built up causing the release of natural gas to the atmosphere from a pipeline overpressure protection valve. Enterprise technicians isolated the valve and it will be replaced. No damage occurred to the pipeline, requiring no further response activities.

Describe Area Affected and Cleanup Action Taken.*

No liquid spills occurred requiring any cleanup actions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by	Signed By 
Title: Director, Field Environmental	Approval Date: 6/2/15	Expiration Date: N/A
E-mail Address: jefields@eprod.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 6-1-2015 Phone: 713-381-6684		

* Attach Additional Sheets If Necessary

2RP-3028

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Monday, June 01, 2015 6:19 AM
To: Bratcher, Mike, EMNRD
Cc: Ferguson, Dina
Subject: 1002 Gathering
Attachments: Eddy County C-141 1002 Gathering Lateral (5-22) June 2015.pdf; Eddy County C-141 1002 Gathering Lateral (5-22) June 2015.pdf

Attached for your review and handling is the C-141 for the subject release. Should you need additional information, please contact Dina Ferguson at 210-528-3824.

Shiver Nolan
Sr. Compliance Administrator

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.