District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

NAB15	1742	1819				OPERA'	ГOR		☐ Initia	il Report		Final Report	
Name of Company Oxy Permian Ltd.							Chancey Summe		· · · · · · · · · · · · · · · · · · ·				
		ive, Midland		Telephone No. (432) 685-5824									
Facility Nar	ne Ceda	ir Canyon 15	Fed Cor	n #5H]]	Facility Type Satellite							
Surface Owner BLM Mineral Owner							API No. 30-15-42421						
				LOCA'	TION	OF RE	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/W	est Line	County			
D	15	24S	29E							Eddy Cour	ıty, NM	,	
			J	Latitude <u>N 32.22</u>	168°	Longitu	de <u>W 103.9802</u>	<u>9°</u>					
				NAT	URE	OF REL	EASE						
Type of Release Oil and produced water							Volume of Release 40 bbls oil, Volume Recovered 100 bbls 100 bbls produced water					ls	
Source of Release A broken water pump coupling caused the water tanks to spill over							Date and Hour of Occurrence Date and Hour of Discovery 05/28/2015						
Was Immediate Notice Given?							If YES, To Whom?						
✓ Yes ☐ No ☐ Not Required													
By Whom? Kathy Purvis, BBC International Was a Watercourse Reached?						Date and Hour 05/29/2015 @ 10:02am NM OIL CONSERVATION If YES, Volume Impacting the Watercourse.							
☐ Yes ⊠ No						ARTESIA DISTRICT							
If a Watercourse was Impacted, Describe Fully.* JUN 2 2 2015												2015	
RECEIVED													
Describe Cause of Problem and Remedial Action Taken.*													
A broken water pump coupling caused the water tanks to spill 40 bbls of oil and 100 bbls of produced water onto the ground. A vacuum truck recovered 100 bbls of fluids and the coupling was replaced.													
Describe Area Affected and Cleanup Action Taken.*													
The affected area is approximately 100' x 45' with most of the leak staying on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
						OIL CONSERVATION DIVISION							
Signature:						$i\Lambda$							
Printed Name: Chancey Summers						Approved by Environmental Specialist:							
Title: HES Lead A							Approval Date: 6 23 15 Expiration Date: NHA						
E-mail Addre	ess: <u>Chan</u>	cey_Summers	@oxy.co	<u>n</u>	(Conditions of	Approval:			Attached			
Date: 6	-18-	15	Phone:	(432) 685-582		Remediation per O.C.D. Rules & Guidelines							
Attach Addit	tional Shee	ets If Necess	ary		S		emediation an: 7/24		Posal 1 ——	2	RP.	3062	

Patterson, Heather, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Monday, June 22, 2015 5:00 PM

To: Cc: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com; C J Summers; Susan Miller

Subject:

Initial C-141, Cedar Canyon 15 Fed Com #5H

Attachments:

Initial C-141, Cedar Canyon 15 Fed Com #5H.pdf

Attached is the initial C-141 for a leak that occurred at the Cedar Canyon 15 Fed Com #5H on 05/28/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com