NM OIL CONSERVATION

State of New Mexico

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District II 811 S. First St., Artesia, NM 88210 District III

District IV

ARTESIA DISTRICT

Form C-141

JUL 1 4 2015 Revised August 8, 2011

Energy Minerals and Natural Resources Oil Conservation Division

1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in RECEIVED NMAC.

Release Notification and Corrective Action

NAB151982144D	OPERATOR	
Name of Company Devon Energy Production 4/37	Contact Garry Michael	
Address 6488 Seven Rivers Hwy Artesia, NM 88220 Telephone No. 575-513-4895		
Facility Name Cotton Draw Unit 134 H Facility Type Oil		
Surface Owner Federal Mineral Owne	r Federal	API No. 30-015-38293
LOCATION OF RELEASE		
Unit Letter Section Township Range Feet from the Nort	h/South Line Feet from the East	/West Line County
M 2 25S 31E 200	South 330	West Eddy
Latitude: N 32'09'10.09" Longitude: W 103'45'22.17"		
NATURE OF RELEASE		
Type of Release Spill Oil	Volume of Release 15 bbl	Volume Recovered
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Contractor was transferring oil and caused an overfill 7.12.2015 @11:52 PM 7.12.2015 @11:52 PM Was Immediate Notice Given? If YES, To Whom?		
By Whom? Lolo Martinez	Date and Hour	
	7.12.2015 2:49 AM 7.12.2015 2:55 AM	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
On July 12, 2015 at 11:52 PM, TCS Trucking Driver was transferring oil from the Cotton Draw 89 SWD to the Cotton Draw Unit 134 H causing an		
overflow of 15 bbls of oil into containment. All 15 bbls were recovered, containment was checked for holes, none were found.		
Describe Area Affected and Cleanup Action Taken.*		
On July 12, 2015 as TCS Trucking employee was transferring oil from the Cotton Draw 89 SWD to the Cotton Draw Unit 134 H, there was an overflow of		
oil, this caused 15 bbls to spill into containment. All 15 bbls of oil were recovered immediately. Containment was checked for holes to make sure there was no leakage, none were found.		
was no leakage, none were found.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger		
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health		
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other		
federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION		
Signature: Corina Moya	Signed By Mile Examples	
Direct Name Code M		
Printed Name: Corina Moya	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: " " "	Expiration Date: NIA
E-mail Address: corina.moya@dvn.com	Conditions of Approval:FINAL	Augebed [7]
Date: 7/14/2015 Phone: 575.746.5559	FINAL	✓ Attached □
* Attach Additional Sheets If Necessary		

Bratcher, Mike, EMNRD

From:

Moya, Corina < Corina. Moya@dvn.com>

Sent:

Tuesday, July 14, 2015 2:34 PM

To:

Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; Sol Hughes (shughes@blm.gov);

stucker@blm.gov

Cc:

Jim Amos (jamos@blm.gov)

Subject:

Cotton Draw Unit 134 H 15 bbl oil spill 7.12.15

Attachments:

Cotton Draw Unit 134 H 15bbl oil spill 7.12.2015 pic 4 of 6.jpg; Cotton Draw Unit 134 H 15bbl oil spill 7.12.2015 pic 5 of 6.jpg; Cotton Draw Unit 134 H 15bbl oil spill 7.12.2015 pic 6 of 6.jpg; Cotton Draw Unit 134 H 15bbl oil spill 7.12.2015 C-141 Initial and Final.doc; Cotton Draw Unit 134 H 15bbl oil spill 7.12.2015 GIS Mapping.pdf; Cotton Draw Unit 134 H 15bbl oil spill 7.12.2015 pic 1 of 6.jpg; Cotton Draw Unit 134 H 15bbl

oil spill 7.12.2015 pic 2 of 6.jpg; Cotton Draw Unit 134 H 15bbl oil spill 7.12.2015 pic 3 $\,$

of 6.jpg

Good afternoon,

Please see the attached C-141 and pics of the incident from the Cotton Draw Unit 134 H 15 bbl oil spill on 7.12.2015

Thank you,

Corina Moya
Field Admin Support
Production
B Schedule

Devon Energy Corporation PO Box 250 Artesia, NM 88211 575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.