NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUL 1 4 2015

Form C-141 Revised August 8, 2011

Submit L Copy to appropriate District Office in RECEI accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action													
NABI	51989		OPERA	ГOR			al Report		Final Report				
Name of Co	mpany: B		Contact: Amy Ruth										
*		mod, Suite 1 Eddy Unit #1		oad, N.M. 88220		Telephone No. 575-887-7329 Facility Type: Exploration and Production							
<i>F</i>				Minoral C									
Surface Owner: Federal Mineral Owner: Federal API No. 30-015-35592													
TI-14 I -41	I C	T	(D			OF REI		T4/1	V4 I !				
Unit Letter			North/ South	South Line	Feet from the 1650	East/West Line East		County Eddy					
Latitude 32.447313° Longitude -104.968975°													
NATURE OF RELEASE Type of Release Crude Oil and Produced Water Volume of Release 1 bbl oil, 6 Volume Recovered													
Type of Rele	ase Crude	Volume of Relcase 1 bbl oil, 6 Volume Rec bbls PW ½ bbl oil, 2											
Source of Release Tank Overflow							Date and Hour of Occurrence 7/5/2015 at 12 am			Date and Hour of Discovery 7/5/2015 at 12 am			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)						
By Whom?		Date and Hour 7/5/2015 at 5:09 pm If YES, Volume Impacting the Watercourse.											
Was a Water	course Read		N/A	olume Impacting t	he Wat	ercourse.							
☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.* BEU 164 well unloaded during the night and tank overflowed into earthen berm containment. Alarm levels were then set during the asternoon on 7/5/2015 to prevent future over flow events.													
Describe Are	a Affected	and Cleanup	Action Tal	cen *									
Describe Area Affected and Cleanup Action Taken.* Leak affected 305 square feet of caliche pad within the earthen containment. Vac truck recovered standing fluids.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws add/or regulations.													
Signature:	Mu	OIL CONSERVATION DIVISION											
Printed Name	e: Amy Ri		Approved by Environmental Specialist.										
Title: Assis	stant Remed		Approval Date: 7/17/15 Expiration Date: NA										
E-mail Addre	ess: ACR		Conditions of Approval:										
	/2015		Pho	ne: 432-661-0571	Remediation	on per O.C.D	. Rule	s & Guid	selines				
* Attach Addi	tional Shee	ets If Necess	ary			ATER TH	EMEDIATION AN:		D_		2RF	- 3126	

Bratcher, Mike, EMNRD

From:

Ruth, Amy C. <ACRuth@BassPet.Com>

Sent:

Tuesday, July 14, 2015 3:13 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc:

jamos@blm.gov

Subject:

Initial C-141 - BEU 164 tank overflow 7-5-15

Attachments:

Initial C-141 - Big Eddy Unit #164 (7-5-2015).pdf

Please find the initial form C-141 for this leak and call me with any questions/concerns. Thanks ©



Amy C. Ruth BOPCO, L.P. EH&S Remediation Specialist 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office: (575)887-7329

Fax: (575)887-7473 Cell: (432)661-0571

From: Ruth, Amy C.

Sent: Sunday, July 05, 2015 5:09 PM

To: Mike Bratcher; EMNRD Patterson Heather

Cc: jamos

Subject: BEU 164 tank overflow 7-5-15

The leak occurred around midnight. I was initially given the wrong lease name this afternoon. I was home before I received an answer on the correct site. I will check it out tomorrow and submit a c-141. Thank you.

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" < <u>DJFuqua@BassPet.Com</u>>
To: "Ruth, Amy C." < <u>ACRuth@BassPet.Com</u>>

Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: big eddy unit 164 bopco l.p. Description: API: 3001535592

Latitude: 32.447678 Longitude: -103.969313 Revised with correct well info.

[image1.jpeg]

Pumper reported spill due to wtr tk overflowing. Vac truck hauled wtr 7/3/15 and well unloaded during the night. Pumper contacted vac truck and recovered 2 bbls wtr from ground and .5 bbls of oil.

Wellkeeper equipment was installed at site but no alarm levels were set up. I will set up high alarms today.

Sent from my iPhone

Sent from my iPhone



Patterson, Heather, EMNRD

From:

Ruth, Amy C. < ACRuth@BassPet.Com>

Sent:

Sunday, July 05, 2015 5:09 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc:

jamos

Subject:

BEU 164 tank overflow 7-5-15

Attachments:

image1.jpeg

The leak occurred around midnight. I was initially given the wrong lease name this afternoon. I was home before I received an answer on the correct site. I will check it out tomorrow and submit a c-141. Thank you.

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" < DJFuqua@BassPet.Com < mailto: DJFuqua@BassPet.Com >>

To: "Ruth, Amy C." < ACRuth@BassPet.Com < mailto: ACRuth@BassPet.Com >>

Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: big eddy unit 164 bopco l.p.

Description: API: 3001535592

Latitude: 32.447678 Longitude: -103.969313

Revised with correct well info.

[image1.jpeg]

Pumper reported spill due to wtr tk overflowing. Vac truck hauled wtr 7/3/15 and well unloaded during the night.

Pumper contacted vac truck and recovered 2 bbls wtr from ground and .5 bbls of oil.

Wellkeeper equipment was installed at site but no alarm levels were set up.

I will set up high alarms today.

Sent from my iPhone

Sent from my iPhone [cid:5:434:0]

1