

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 14 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1519854325

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Indian Flats Bass Federal #4 at Indian Flats Bass Federal SWD (SWD is located 2996 ft. SW of Well #1 API 30-015-24968)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-22229
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 35	Township 21S	Range 28E	Feet from the 1652	North/South Line South	Feet from the 2150	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.433934° Longitude -104.056149°

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 1/4 bbl oil, 5 bbls PW	Volume Recovered None
Source of Release Poly flow line	Date and Hour of Occurrence 7/4/15 hour unknown	Date and Hour of Discovery 7/4/15 8 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD) and Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour 7/4/15 5:23 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Poly line ruptured by unknown cause. Poly line was clamped and the well was shut-in until the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The leak affected 525 square feet of pasture located just west of the Indian Flats Bass Federal SWD pad.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Signed By <i>[Signature]</i> Approved by Environmental Specialist	
Title: Assistant Remediation Foreman	Approval Date: 7/17/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/14/2015	Phone: 432-661-0571	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:

8/20/15

2RP-3127

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Tuesday, July 14, 2015 3:10 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos@blm.gov
Subject: Initial C-141 - Indian Flats Bass Federal #4 flow line leak 7-4-15
Attachments: Initial C-141 - Indian Flats Bass Fed #4 (7-4-15).pdf

Please find the attached initial form C-141 and call me with any questions/concerns... Thanks ☺

From: Ruth, Amy C.
Sent: Saturday, July 04, 2015 5:23 PM
To: Mike Bratcher; 'Patterson, Heather, EMNRD'
Cc: jamos@blm.gov
Subject: Indian Flats Bass Federal #4 flow line leak 7-4-15

Our poly flow line ruptured and was discovered this morning at about 8 am. The GPS location is represented on the photo. The line was clamped and the well was shut in until the section can be replaced. The leak (oil and produced water) affected 525 square feet of pasture located just west of our North Indian Flats Battery. The leak is most likely just over 5 bbls. Volume will be confirmed and a C-141 will be submitted if needed. Thanks!



Amy C. Ruth
BOPCO, L.P.
EH&S Remediation Specialist
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office: (575)887-7329
Fax: (575)887-7473
Cell: (432)661-0571

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Saturday, July 04, 2015 5:23 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos@blm.gov
Subject: Indian Flats Bass Federal #4 flow line leak 7-4-15
Attachments: Image with leak area.jpg; IMG_0731.JPG

Our poly flow line ruptured and was discovered this morning at about 8 am. The GPS location is represented on the photo. The line was clamped and the well was shut in until the section can be replaced. The leak (oil and produced water) affected 525 square feet of pasture located just west of our North Indian Flats Battery. The leak is most likely just over 5 bbls. Volume will be confirmed and a C-141 will be submitted if needed. Thanks!



Amy C. Ruth

BOPCO, L.P.

EH&S Remediation Specialist

522 W. Mermod, Suite 704

Carlsbad, NM 88220

Office: (575)887-7329

Fax: (575)887-7473

Cell: (432)661-0571