

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520453746

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #074	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31168
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 6	Township 23S	Range 31E	Feet from the 330	North/South Line North	Feet from the 430	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.339824° Longitude W 103.824221°

NATURE OF RELEASE

Type of Release: Crude oil & Produced Water	Volume of Release: 3 bbls. oil & 11 bbls. PW	Volume Recovered: 2 bbls. oil & 1 bbl. PW
Source of Release: 1/4" Pressure gauge	Date and Hour of Occurrence: 7/25/15 time unknown	Date and Hour of Discovery: 7/25/15 at approximately 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 28 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 1/4" gauge on the wellhead failed internally releasing oil and water on to the wellhead pad. A valve to the gauge was shut until the gauge could be replaced.

Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 365 sq. ft. of the bermed wellhead and pad area. All of the free standing fluid was recovered with a vacuum truck. The stained area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: [Signature]	
Title: Waste Management and Remediation Specialist	Approval Date: 7/28/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/28/15 Phone: 432-556-8730	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/30/15

* Attach Additional Sheets If Necessary

2RP-3165

Patterson, Heather, EMNRD

From: Savoie, Tony A. <TASavoie@BassPet.Com>
Sent: Tuesday, July 28, 2015 5:57 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos (James_Amos@blm.gov)
Subject: JRU-74 C-141
Attachments: Initial C-141 (7-28-15).pdf

All, please find the attached C-141 for a wellhead spill dated 7/25/15 at the JRU-74 (API-30-015-31168) All of the fluid released was contained on the well pad.

Regards,
Tony