

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 06 2015

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Holly Energy Partners	Contact: Bill Green (no longer w/ HEP)
Address: 1602 W. Main Artesia, NM 88210	Telephone No.
Facility Name: Beeson Pump Unit 1	Facility Type: Crude Oil Pumping Station

Surface Owner: BLM	Mineral Owner:	API No.
--------------------	----------------	---------

LOCATION OF RELEASE

2RP-2016

Unit Letter C	Section 3	Township 18S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.4655.29° Longitude 103.573598°

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release 15 bbls	Volume Recovered 0
Source of Release: Seal failure	Date and Hour of Occurrence 10/18/13 06:45 A.M.	Date and Hour of Discovery 10/18/2013 06:45 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, To Whom? Unknown	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A Pump seal failure in the #1 unit is the cause if release. Pumping sources immediately shut down. Failure resulted in a vertical spray of crude oil mist. Impacted soils at the source were excavated and placed on a liner for disposal at an NMOCD approved facility. SESI was retained for complete remediation of the site.

Describe Area Affected and Cleanup Action Taken.*

The affected area was excavated according to the NMOCD approved work plan. Regulatory documentation was submitted to the NMOCD for closure of the incident on 04-28-14.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Allison Stockweather</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>Allison Stockweather</i>		Approved by District Supervisor: <i>H. [Signature]</i>	
Title: <i>EHS Senior Manager</i>		Approval Date: <i>7/8/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>allison.stockweather@hollyenergy.com</i>	Date: <i>07/09/15</i>		Phone: <i>505-573-9338</i>
Conditions of Approval: <i>Final</i>		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2016