

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1524653994

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company ConocoPhillips	Contact Wendy Acosta Quintero	
Address 3300 North A Street, Midland, TX 79707	Telephone No. 432-688-9162	
Facility Name Stampede Federal 34-1H	Facility Type Production Facility	
Surface Owner	Mineral Owner	API No. 30-005-42123

LOCATION OF RELEASE

Unit Letter	Section 34	Township 26S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

32.001006

Latitude **32° 00' 03"**

Longitude **-103° 46' 24"**

103.773846

NATURE OF RELEASE

Type of Release oil/Produced water	Volume of Release 11 bbl	Volume Recovered 6 bbl
Source of Release Separator	Date and Hour of Occurrence	Date and Hour of Discovery 07/22 1630
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD - Tomas Overding, BLM - Jim Amis	
By Whom? Wendy Acosta Quintero	Date and Hour 07/23/2014 10 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* At approximately 4:00 PM, separator pressure was adjusted, which caused the flare at the battery to go out. When a cloud of gas coming from one of the separator lines was noticed, well was shut in.		
Describe Area Affected and Cleanup Action Taken.* After deeming safe conditions, lines were checked to identify leak source and a hole approximately 1 1/2 inches in diameter on the underside of the pipe from the water leg was noticed. It made a hole on the ground about two feet in diameter and 1 1/2 feet deep and spilled approximately 11 bbls (9 bbl produced water and 2 bbl oil).		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:		OIL CONSERVATION DIVISION
Printed Name: Wendy Acosta Quintero		Approved by Environmental Specialist: [Signature]
Title: Graduate Environmental Specialist		Approval Date: 9/3/15 Expiration Date: N/A
E-mail Address: wendy.acostaquintero@cop.com		Conditions of Approval:
Date: 7/23/2015 Phone: 432-688-9162		Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO

* Attach Additional Sheets If Necessary

LATER THAN: **10/4/15**

2RP-3236