

District I
1623 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526427787 USA WTP OPERATOR ☒ Initial Report ☒ Final Report

Name of Company Bridger Logistics	Contact Robert Franklin
Address 2009 Chenault Drive, Carrollton, TX 75006	Telephone No. 915-801-6129
Facility Name Piglet 21 State # 001	Facility Type Tank Battery
Surface Owner State	Mineral Owner State
API No. 30-015-39371	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	21	17S	28E	1627	S	345	E	Eddy

Latitude 32.8172073 Longitude -104.1734238

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 3.25	Volume Recovered 3
Source of Release Truck	Date and Hour of Occurrence: 08-21-2015 at 8:15 PM	Date and Hour of Discovery: 08-21-2015 at 8:21 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?: National Response Center, NMED, Eddy County LEPC	
By Whom?: Ernest Spencer, ACE Spill Center	Date and Hour: 08-21-2015, at 9:36 PM, 9:45 PM and 9:50 PM respectively	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Human error caused the oil truck to overflow, resulting in a release of 3.25 bbls of crude oil. Talon/LPE mobilized personnel to contain the impacted area and to prevent any further migration of contamination. A vacuum truck was used to recover the standing fluid. Approximately 3 bbls were recovered.		
Describe Area Affected and Cleanup Action Taken.* The impacted area was contained to the well pad. A backhoe was utilized to excavate the impacted material using PID readings and chloride titrations to guide the excavation. All of the excavated material was hauled to a NMOCD approved solid waste disposal facility. The release did not meet the minimum volume requirements to be reported to the NMOCD. Therefore, once field data indicated that all of the impacted soil was removed, the excavation was backfilled and contoured to match the surrounding location.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Robert Franklin</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Franklin	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: WTX Field Safety REP	Approval Date: <i>9/21/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: rfranklin@bridgergroup.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: September 8, 2015	Phone: 915-801-6129	

* Attach Additional Sheets If Necessary

2RP 3267

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 15 2015

RECEIVED



SPILL CENTER

September 8, 2015

Mr. Cory Smith, Environmental Specialist
New Mexico Oil Conservation Division
District III - Aztec
1000 Rio Brazos Road
Aztec, NM 87410

OIL CONS. DIV DIST. 3

SEP 11 2015

RE: Generator: Bridger Logistics
Loss Location: Artesia, New Mexico
Loss Date: August 21, 2015
Spill Center Claim Number: B15082103
Incident Number: 8279329

Dear Mr. Smith:

Attached please find the Form C-141 regarding the above-referenced loss.

Please contact me if you require additional information at 978-568-1922, Ext. 244.

Very truly yours,

Ernie Spencer,
Compliance Associate

ES
Enclosures

CC: Mr. Robert Franklin, Bridger Logistics