State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification	on and Cor		tion		
NAB1526632314	OPERAT(_	l Report	Final Report
Name of Company Linn Operating Inc. 209324		E.L. Gonzales		ricepon	
Address 2130 W Bender Blvd Hobbs, NM 88240		Telephone No. 575-738-1739			
Facility Name Russell Turner WS (Turner B #42 closest well)		Facility Type Water Station			
Surface Owner Federal Mineral Own	er		API No	o. closest v	well 30-015-05278
·····	ON OF RELI	FASIF			
	orth/South Line	Feet from the	East/West Line	County	
$\begin{array}{c c} E \\ E \\ 20 \\ 17S \\ 31E \\ 1650 \\ 1650 \\ \end{array}$	North	330	West	County	Eddy
Latitude32.82274		103 8994446	l		
;	E OF RELEA				
ype of Release Produced Water		Release 5bbls	Volume I	Recovered	0
Source of Release Flow line		Date and Hour of Occurrence		Date and Hour of Discovery	
	09/10/2015		09/10/20		
Was Immediate Notice Given?	red If YES, To	Whom?		NM	Ο μ.
By Whom?	Date and H	lour			ADD CONSEDU
Was a Watercourse Reached?	If YES, Vo	lume Impacting	the Watercourse.		TESIA DISTRIC
🗌 Yes 🛛 No					SEP 10
	I				RECEIVED
Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab	out 100 yards east	t of dirt road head			OIL CONSERVA ARTESIA DISTRICT SEP 1 8 2015 RECEIVED
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab 10 ft. X 10 Ft. Approx. 5 Bbl. Spilled. Describe Area Affected and Cleanup Action Taken.* 10' x 10'	out 100 yards east	t of dirt road head			
Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab 10 ft. X 10 Ft. Approx. 5 Bbl. Spilled. Describe Area Affected and Cleanup Action Taken.* 10' x 10' I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain relea public health or the environment. The acceptance of a C-141 report b should their operations have failed to adequately investigate and reme or the environment. In addition, NMOCD acceptance of a C-141 report	to the best of my se notifications ar y the NMOCD ma diate contamination	knowledge and u nd perform correc arked as "Final R on that pose a thr	ding north of Russe inderstand that purs ctive actions for rel eport" does not rel eat to ground wate	suant to Ni leases whic lieve the op r, surface v	SWD. Found Leak at MOCD rules and th may endanger perator of liability vater, human health
Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab 10 ft. X 10 Ft. Approx. 5 Bbl. Spilled. Describe Area Affected and Cleanup Action Taken.* 10' x 10' I hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain relea public health or the environment. The acceptance of a C-141 report b should their operations have failed to adequately investigate and reme or the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations.	to the best of my se notifications ar y the NMOCD ma diate contamination	knowledge and u nd perform correc arked as "Final R on that pose a thr e the operator of	ding north of Russe inderstand that purs ctive actions for rel eport" does not rel eat to ground wate	ell Turner S suant to NI leases whic lieve the op er, surface v compliance	SWD. Found Leak at MOCD rules and th may endanger perator of liability vater, human health with any other
Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab 10 ft. X 10 Ft. Approx. 5 Bbl. Spilled.	to the best of my se notifications ar y the NMOCD ma diate contamination ort does not relieve	knowledge and u nd perform correc arked as "Final R on that pose a thr e the operator of	ding north of Russe inderstand that pur- ctive actions for rel eport" does not rel eat to ground wate responsibility for c SERVATION	ell Turner S suant to NI leases whic lieve the op er, surface v compliance	SWD. Found Leak at MOCD rules and th may endanger perator of liability vater, human health with any other
Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab 10 ft. X 10 Ft. Approx. 5 Bbl. Spilled. Describe Area Affected and Cleanup Action Taken.* 10' x 10' hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain relea public health or the environment. The acceptance of a C-141 report b should their operations have failed to adequately investigate and reme or the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations.	to the best of my se notifications ar y the NMOCD ma diate contamination ort does not relieve	knowledge and u nd perform correc arked as "Final R on that pose a thr e the operator of OIL CON Environmental S	ding north of Russe inderstand that pur- ctive actions for rel eport" does not rel eat to ground wate responsibility for c SERVATION	suant to NI leases whice lieve the op or, surface v compliance	SWD. Found Leak at MOCD rules and th may endanger perator of liability vater, human health with any other
Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab 10 ft. X 10 Ft. Approx. 5 Bbl. Spilled. Describe Area Affected and Cleanup Action Taken.* 10' x 10' hereby certify that the information given above is true and complete regulations all operators are required to report and/or file certain relea public health or the environment. The acceptance of a C-141 report b should their operations have failed to adequately investigate and reme or the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations.	to the best of my se notifications ar y the NMOCD ma diate contamination ort does not relieve Approved by Approval Date Conditions of	knowledge and und perform correct arked as "Final R on that pose a thr e the operator of <u>OIL CON</u> Environmental S e: <u>4123115</u>	ding north of Russe inderstand that pur- ctive actions for rel eport" does not rel eat to ground wate responsibility for c SERVATION pecialist:	suant to NH leases whice lieve the op r, surface v compliance DIVISI Date: N	SWD. Found Leak at MOCD rules and th may endanger perator of liability vater, human health with any other ON
Describe Cause of Problem and Remedial Action Taken.* Was Looking for inj. Leak, Drove out Main header line found leak ab 0 ft. X 10 Ft. Approx. 5 Bbl. Spilled. Describe Area Affected and Cleanup Action Taken.* 10' x 10' hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain relea public health or the environment. The acceptance of a C-141 report b hould their operations have failed to adequately investigate and reme or the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations. Fignature: Printed Name: E.L. Gonzales Title: Production Supervisor	to the best of my se notifications ar by the NMOCD ma diate contamination ort does not relieve Approved by Approval Date Conditions of	knowledge and und perform correct arked as "Final R on that pose a three the operator of <u>OIL CON</u> Environmental S e: <u>412311</u> Approval:	ding north of Russe inderstand that pur- tive actions for rel eport" does not rel responsibility for c SERVATION pecialist:	suant to NI leases whice lieve the op r, surface v compliance DIVISI Date: N Attache ejines	SWD. Found Leak at MOCD rules and th may endanger perator of liability vater, human health with any other ON

Patterson, Heather, EMNRD

From: Sent: To: Cc:	McCracken, Theresa <tmccracken@linnenergy.com> Friday, September 18, 2015 10:27 AM Patterson, Heather, EMNRD; stucker@blm.gov Butters, Thomas; Gonzales, EL; Moreno, Laura; Hickert, Aaron; Rivera, Albert; Michael Burton</tmccracken@linnenergy.com>
Subject:	Linn- Russell Turner WS TB#42 9-10-15
Attachments:	IMG_0014.JPG; IMG_0015.JPG; IMG_0016.JPG; Russell Turner Leak TB #42 9-10-15.pdf

All,

Please find attached the initial C-141 for the above referenced location.

Thank you,



NASDAG:LINE NASDAQ:LNCO

Theresa McCracken

Field Administrator LINN Energy, LLC 2130 W Bender Hobbs, NM 88240 T: 575-738-1739 / F: 575-738-1740 tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.