Para se	1625 N. French Dr., Hobbs, NM 88240	-	f New Mexico s and Natural Resources				Form C-141 Revised October 10, 2003			
12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	District IIIOil Conservation Division1000 Rio Brazos Road, Aztec, NM 874101220 South St. Francis Dr.District IV1220 South St. Francis Dr.1220 S. St. Francis Dr., Santa Fe, NM 87505Santa Fe, NM 87505						Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form			
	Release Notification and Corrective Action									
	OPERATOR Initial Report Final Report Name of Company St Mary Land & Exploration Co. Contact Donna Huddleston Address 3300 N. A Street, Bldg. 7, Ste. 200, Midland, TX 79705 Telephone No. 432-688-1789 Facility Name Parkway Delaware Unit #513 Facility Type Injection									
F	Surface Owner BLM Mineral Owner BLM				Lease No. NMNM88491X					
Surface Owner BLM Mineral Owner BLM Lease No. NMNN LOCATION OF RELEASE										
- Terrer	Unit Letter Section Township Range Feet from the No. J 35 19S 29E	orth/\$	South Line	Feet from the	East/\	Vest Line	ne County Eddy			
1 23	Latitude									
	NATURE OF RELEASE Type of Release Produced Water Volume of Release 50 BW V						Volume Recovered 0			
~9	Source of Release 2.5" flanged Balon trunk line valve.		Date and H	our of Occurrence	e	Date and I	Hour of Discovery			
	Was Immediate Notice Given?	2/25/09 7:30 AM 2/25/09 7:30 AM If YES, To Whom? Mike Bratcher w/NMOCD & Jim Amos w/BLM If YES, To Whom?								
	By Whom? Bill Hearne Was a Watercourse Reached?		Date and Hour 2/25/2009 10:20 AM If YES, Volume Impacting the Watercourse.							
	🗌 Yes 🛛 No	, , , , , , , , , , , , , , , , , , , ,								
Notice of	If a Watercourse was Impacted, Describe Fully.*									
	Describe Cause of Problem and Remedial Action Taken.* Cause: 2.5" flanged Balon trunk line valve failure (bottom of valve blow out) @ junction box. Injection pumps shut down on low (900#) injection pressure. Estimated 50 bbls, Produced water spilled									
	Describe Area Affected and Cleanup Action Taken.* West of Injection Station and north of PDU #513. Spill Area: 180' x 70' = 12,600 sq. ft. Dug out contaminated soil and remediate with fresh soil.									
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health environment.									
	or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.									
				<u>OIL CONS</u>	<u>ERV</u>	ATION I 1	$\frac{1}{2}$	<u>N</u>		
CONSIGNATION OF THE PARTY OF TH	Signature: Printed Name: Tim Reed (agent for St. Mary Land)		Approved by District Supervisor: Machine							
	Title: Tetra Tech	A	Approval Date: 11/4/15			Expiration Date: N/A				
(1999) 	E-mail Address: timothy.reed@tetratech.com		onditions of a	Approval:						
Ĩ	Date: 6/01/2009 Phone: 432-682-4559	1	Final				Attached			
3* Attach Additional Sheets If Necessary CRP-Co90										

a colore for the second