<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

District IV 1220 S. St. Francis Dr., Sandary 2, M. 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

FAB160295528 RECEIVED Release Notification and Corrective Action													
NAB 1602	95654	2				OPERA				al Report		Final Report	
Name of Co				<u>Onshore, LLC</u>	(Contact	Cort Farme						
Address 831 S. East Ave, Kermit, TX 79745 Telephone No. (432) 425-5295													
Facility Name Legacy Gathering System							Facility Type Natural Gas Gathering Pipeline						
Surface Ow	mer BI	BLM API No.											
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
Unit Letter	Section	Township	h/South Line Feet from the East/West Line County										
P_{-}	26	265	295							Edd	<u>/</u>		
Latitude 32.005116 Longitude -103.947281													
NATURE OF RELEASE													
Type of Release Natural Gas Condensate							Volume of Release 15 bbl Volume Recovered 0 bbl						
Source of Release Natural Gas Pipeline Was Immediate Notice Given?							Occurrence: 1/14/16 0200 Discovery: 1/14/16 0600 If YES, To Whom?						
vv as minecula	ate Notice o		Yes 🗌	No X Not Req	ii 1 Lo, 10 wiloiti.								
By Whom?						Date and Hour							
Was a Watercourse Reached? ☐ Yes 🔀 No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Francis, and a second s													
						,							
Describe Cause of Problem and Remedial Action Taken.* A faulty gate valve allow the mid-pressure system to flow into the low pressure system flowline, causing the flowline													
to overpressure and rupture. Impacted soil was scraped off the road and stockpiled on location. The site will be													
delineated and remediated on-site.													
Describe Are	a Affected a	nd Cleanup A	Action Take	en.* line Road, who	ere it	migrated	down the roa	ıdway.	Impact	ed mater	ial wa	as	
						_		•	_				
mechanically scraped rom road surface to avoid interference with traffic. Impacted material was stockpiled on location.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
							OIL CONS	SERV.	<u>ATION</u>	DIVISIO	<u> N</u>		
Signature:								11/1	1 1				
Printed Name: Cort Farmer						Approved by	Signed By Environmental-Sp	occialist:	L) reson	Teleste_			
	E Repres	entative				Approval Dat	e: 1/29/1/0	E	xpiration	Date: \/)		
E-mail Addre	ess' cort		Canditions of	Annraval									
1/15/16 (423) 425 5205						Remediation per O.C.D. Rules & Guidelinetsached SUBMIT REMEDIATION PROPOSAL NO							
Attach Addit		ts If Necess		<u>* </u>	LATER THAN: 31116 200-3526								
			•		-	# 14 MAIN 1 1 1 1 7				U	W	2540	