



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1605631986

1RP - 2887

SOUTHERN UNION GAS SERVICES LTD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Southern Union Gas Services	Contact	Rose Slade
Address	801 S. Loop 464, Monahans, TX 79756	Telephone No.	432-940-5147
Facility Name	Fullerton 6" (Osborne) Pipeline	Facility Type	Natural Gas Pipeline
Surface Owner :	Clay Osborne	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	35	21	37					Lea

Latitude 32 degrees 25.697' North **Longitude** 103 degrees 07.935' West

NATURE OF RELEASE

Type of Release	Natural Gas, Crude Oil and Produced Water	Volume of Release	35bbls	Volume Recovered	None
Source of Release	6" Natural Gas Pipeline	Date and Hour of Occurrence :	12/12/2012 @ 10:15 AM	Date and Hour of Discovery	December 12, 2012- 10:15 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoff Leking		
By Whom?	Rose Slade	Date and Hour	12/12/2012 @ 1:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A 6" steel pipeline was struck by a contractor causing liquids and an overspray of crude oil with a mixture of produced water to impact the soil in the area.					
Describe Area Affected and Cleanup Action Taken.* Area impacted was a radius of 2000x650. Micro-blaze was applied with a surfactant to loosen the hydrocarbon impaction of the impacted soils. An environmental consultant will remediate this site per NMOCD regulatory standards and the landowner was notified of the release.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Rose Slade	Approved by Environmental Specialist:		
Title: Environmental Specialist	Approval Date:	Expiration Date:	
E-mail Address: rose.slade@sug.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: December 17, 2012	Phone: 432-940-5147	IRP# 2887	

* Attach Additional Sheets If Necessary