



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1606052592

1RP - 3101

APACHE CORP

2/29/2016

MAR 01 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
Revised October 10, 2003

SEP 07 2010
HOBSOCD
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name EBDU Sat #1 Nearest well EBDU #6	Facility Type Production Facility
Surface Owner McNeil	Mineral Owner State of NM
Lease No. 30-025-30469	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	1	21S	37E	4195'	FNL	2310'	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 80	Volume Recovered 74
Source of Release Water Tank	Date and Hour of Occurrence 08/30/2010 7:15am	Date and Hour of Discovery Same
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left message for Geoffrey	
By Whom? Natalie Gladden	Date and Hour 08/30/2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 60'



Describe Cause of Problem and Remedial Action Taken.*

8' open top water tank filled up and ran over. Victory Services is contracted to do scheduled hauling at this facility, they failed to do so; therefore the water tank overflowed and released the fluid inside the lined containment.

Describe Area Affected and Cleanup Action Taken.*

The fluid was released inside the lined containment. The fluid was removed along with the pea gravel covering the liner. The pea gravel was hauled to Sundance Services; liner was found to be intact and area was backfilled. No sampling required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District Supervisor:  Environmental Specialist	
Title: EHS Environmental Tech	Approval Date: 09/07/10	Expiration Date: . . .
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: -	Attached <input type="checkbox"/>
Date: 09/01/2010 Phone: 575-390-4186	WRP-06-14-3101	

* Attach Additional Sheets If Necessary