

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 22 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: HARPER STATE #001	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-30831
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 16	Township 17S	Range 30E	Feet from the 430'	North/South Line South	Feet from the 330'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.8285027 Longitude -103.9695053

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 13 bbls	Volume Recovered: 11 bbls
Source of Release: Heater treater	Date and Hour of Occurrence: 4/6/2016 12:00pm	Date and Hour of Discovery: 4/6/2016 12:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the firetube. A vacuum truck was dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the bermed facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>H. Grubbs</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>4/25/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	
Date: April 21, 2016	Remediation per O.C.D. Rules & Guidelines <input checked="" type="checkbox"/> Attached <input type="checkbox"/>	
Phone: 432-683-7443	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: *5/26/16* *2RP3657*

* Attach Additional Sheets If Necessary.

Patterson, Heather, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Friday, April 22, 2016 11:36 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'agroves@slo.state.nm.us'; 'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.
Subject: (Notification) Harper State #1 (30-015-30831)
Attachments: 4-6-2016 Harper State #1 (TB) Initial.pdf

MR. BRATCHER,

COG OPERATING LLC IS REPORTING A RELEASE ON THE HARPER STATE #1 (30-015-30831)
SECTION 16 TOWNSHIP 17S RANGE 30E
THE RELEASE OCCURRED AT 12:00 PM ON 4/6/2016
RELEASED: 13 BBLs PW
RECOVERED: 11 BBLs PW

THIS RELEASE WAS CAUSED BY A HOLE IN THE FIRE TUBE. A VACUUM TRUCK WAS DISPATCHED TO RECOVER STANDING FLUID. ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.
SR. ENVIRONMENTAL COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.661.6601 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.