

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 01 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1618835036

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: SEABISCUIT FEDERAL Battery	Facility Type: Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-41563	

LOCATION OF RELEASE

Unit Letter N	Section 12	Township 24S	Range 31E	Feet from the 330'	North/South Line South	Feet from the 2200'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude/Longitude 32.2255325,-103.732933

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 10 bbls oil	Volume Recovered: 8 bbls oil
Source of Release: Broken sight glass	Date and Hour of Occurrence: 6/26/2016 unknown	Date and Hour of Discovery: 6/26/2016 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a broken sight glass on the heater treater. A vacuum truck was dispatched to recover all the standing fluid and excavate gravel.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>7/1/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: June 30, 2016 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *8/7/16* *ARP-3760*

Patterson, Heather, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Thursday, June 30, 2016 1:30 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; James_Amos@blm.gov; Shelly Tucker
Subject: (Notification/C-141 Initial) SEABISCUIT FEDERAL BATTERY (30-015-41563)
Attachments: 6-26-2016 Seabiscuit Federal Battery (TB) Initial.pdf

Mr. Bratcher/Ms. Tucker,

COG Operating LLC is reporting a release on the SEABISCUIT FEDERAL BATTERY (30-015-41563)
Unit N Section 12 Township 24S Range 31E
The release occurred on 6/26/2016
Released: 10 bbls Oil
Recovered: 8 bbls Oil

This release was caused by a broken sight glass and occurred within a lined containment. Vacuum trucks were dispatched to recover all the standing fluid. Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis
Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

1401 Commerce Drive
Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.