

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88211
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

NOV 07 2012

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Tracy Kidd
Address P. O. Box 250 Artesia, NM 88211	Telephone No. 575-748-0189
Facility Name Rio Blanco #33 Federal #1	Facility Type Gas Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

30 025 36359

Unit Letter N	Section 33	Township 22S	Range 34E	Feet from the 1000	North/South Line South	Feet from the 1620	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 290 bbls	Volume Recovered 290 bbls
Source of Release Overflowed Tank	Date and Hour of Occurrence 11/3/12, 8:45AM	Date and Hour of Discovery 11/3/12, 8:45AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.* At the Red Bull 31 Battery, the contract pumper noticed the tank running over into the lined containment causing a spill of 290 barrels of produced water, no alarm was given due to a scada upgrade.

Describe Area Affected and Cleanup Action Taken.* At the Red Bull 31 Battery, the contract pumper noticed the tank running over into the lined containment causing a spill of 290 barrels of produced water, no alarm was given due to a scada upgrade. Contract pumper immediately notified a vacuum truck to recover all 290 barrels of fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Graciela C. Bustamante</i>	<div>OIL CONSERVATION DIVISION</div> <div>APPROVED</div> <div>9/1/16</div>
Printed Name: Graciela C. Bustamante	
Title: Field Adm. Support	
Date: 11/06/12 Phone: (575) 746-5561	
Conditions of Approval:	

* Attach Additional Sheets If Necessary

128-4322