



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1603631025

1RP - 4151

CIMAREX ENERGY CO. OF COLORADO

7/29/2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Cimarex Energy Co	Contact John Osbourne
Address 600N Marienfeld, Ste 600, Midland, TX 79701	Telephone No. 575-390-8978
Facility Name Mallon 34 Federal #1	Facility Type Well

Surface Owner BLM	Mineral Owner	API No. 30-025-32605
--------------------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	34	19S	34E					Lea

Latitude 32.6205 Longitude -103.5354

NATURE OF RELEASE

Type of Release Oil	Volume of Release Est 10 BBLs	Volume Recovered Est 1 BBL
Source of Release Flow Line	Date and Hour of Occurrence 19Feb12 Hr unknown	Date and Hour of Discovery 19Feb12 1300hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A



GW @ 160'

Describe Cause of Problem and Remedial Action Taken.*

Failure of a flowline caused an unplanned release of oil. A vacuum truck was dispatched to attempt recovery of free standing liquid. Remedial action to recover saturated soil will commence as soon as OK is given by BLM. Upon completion of the remedial action to prevent further migration and penetration, a remediation work plan will be submitted for review/approval.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John Osbourne	Approved by Environmental Specialist: 	
Title: FOREMAN	Approval Date: 2/21/12	Expiration Date: 4/23/12
E-mail Address: j.osborne@cimarex.com	Conditions of Approval: SUBMIT FINAL C-141 BY 4/23/12,	Attached <input type="checkbox"/> IRP-2-12-2783
Date: 20Feb12	Phone: 575-390-8978	

* Attach Additional Sheets If Necessary

4151