



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1620944839

1RP - 4363

CANO PETRO OF NEW MEXICO, INC.

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 07 2011

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cano Petro of New Mexico, Inc.	Contact	Rodger Butts
Address	6500 N. Belt Line Road #200, Irving TX 75063	Telephone No.	575-703-5730
Facility Name	Cato #6 Battery	Facility Type	Battery
Surface Owner	Private/FED	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	11	8S	30E	1980	FSL	660	FWL	Chaves

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Salt Water and Oil	Volume of Release	approx 30 bbls of oil and 300 bbls of water	Volume Recovered	
Source of Release	Water tanks	Date and Hour of Occurrence	06-03-11, sometime between midnight & 5:00 am	Date and Hour of Discovery	06-03-11, 5:30 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jerry Dutchover at the BLM Roswell Field Office		
By Whom?	Sandra Durazo	Date and Hour	06-03-11, 5:00p.m.		
Was a Watersource Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watersource was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Cause of Problem: Loss of electricity to the pumps caused the spillage.					
Remedial Action: Some of the wells were still producing and they were shut-down to stop production until electricity could be restored.					
Describe Area Affected and Cleanup Action Taken.*					
Spill originated at GPS coordinates 083.63242 N, 103.85914 W to 033.63455 N, 103.86313W; and encompassed an area of 4,482 ft x 440 ft.					
Area Affected: Around the tanks and runoff down the road and into pasture.					
Cleanup Action: Picking up all liquids, will use a backhoe to remove the affected soil.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
OIL CONSERVATION DIVISION					
Signature:	<i>Rodger Butts</i>				
Printed Name:	Rodger Butts				
Title:	Production Foreman				
E-mail Address:	rodger@canopetro.com				
Date:	06-03-2011				
Phone:	575.703.5730				
Approved by District Supervisor:		Approval Date:		Expiration Date:	
Conditions of Approval:		Attached		<input type="checkbox"/>	

* Attach Additional Sheets If Necessary

30 005
20001



CANO SPILL

6/07/2011

HOBBS OCD

JUN 08 2011



No Warranty is made by the Bureau of Land Management as to the accuracy, reliability, or completeness of these data for individual use or aggregate use with other data, or for purposes not intended by the BLM. Spatial information may not meet National Map Accuracy Standards. This information is subject to change without notification.

