## NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 05 2016

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

**RECEIVED** 

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505													
Release Notification and Corrective Action													
NAB 1422/35529						OPERATOR			Initial Report  Final Report				
Name of C	ompany	Hanley F	9 <i>20</i>	ContacBre		CS_ III(II	u. report	<u></u>	i mai recpor				
Address 415 W. Wall Street, Suite 1500 Telephone No. 432-684-8051													
Facility Na	me St	ate 32	#1			Facility Typ	e Oil wel	1				· · · · · · · · · · · · · · · · · · ·	
Surface Owner Unknown Mineral Owner State of New Mexico API No. 30-015-29378													
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	est Line	County			
D	32	19S	31E	600	F	NL	600	F	FWL Eddy				
	J			tituda		I amaia		٠					
LatitudeLongitude													
NATURE OF RELEASE  Type of Release oil. possible salt water Volume of Release Unknown Volume Recovered None													
Source of Re			Volume of Release Unknown   Volume Recovered   None     Date and Hour of Occurrence   Date and Hour of Discovery										
Was Immedi		liven?		ad, Engine		If YES, To Whom?							
Yes 🛛 No 🗌 Not Required													
By Whom?	course Reac	hed?		Date and Hour  If YES, Volume Impacting the Watercourse.									
Was a Watercourse Reached?						11 1135, VC	nume impacting t	ine water	course.				
If a Watercou	irse was Im	pacted, Descr	ibe Fully.			<u> </u>							
B 1 - 0	- CD11		15 1 4				,						
Describe Cause of Problem and Remedial Action Taken.*  Oil mist from gas vent, gas venting due to high line pressure. Various small flowline													
leaks, minor stuffing box leaks and engine oil.													
		Ŭ			_		,						
1	Describe Area Affected and Cleanup Action Taken.* All leaks appear minor and only effecting surface. No												
samples	have b	een take	or te	sted at th	is t	ime. Ma	y plug wel	1 and	do fi	nal cle	an ı	ıp of	
entire :	_			e. If con	tinu	e to pro-	duce, effe	cted	areas	W1TT D€	; CTE	eaned	
up accor	rding to fy that the in	o OCD ru	ren above	is true and compl	ete to ti	he best of my	knowledge and m	nderstand	that nure	uant to NM	OCD r	ules and	
regulations all	l operators a	ire required to	report an	d/or file certain re	elease n	otifications an	d perform correct	tive actio	ons for rele	ases which	may er	ndanger	
public health of should their o	or the envir serations ha	onment. The	acceptance dequately	of a C-141 repoinvestigate and re	rt by the mediate	e NMOCD ma e contaminatio	rked as "Final Re	eport" do est to aro	es not relie	eve the oper	rator of ster bu	fliability man health	
or the environ	ment. In ac	ldition, NMO	CD accept	ance of a C-141 r	eport d	oes not relieve	the operator of r	responsib	ility for co	mpliance v	vith any	other	
federal, state,	or local law	s and/or regu	lations.				OIL CONG	CEDV	TION	DIVICIO	)NI		
/	1 and	<del>-4-1</del>		OIL CONSERVATION DIVISION									
Signature:		f ff		Approved by Environmental Specialist:									
Printed Name:	Brett	K. Brack		Approved by I	Environmental Sp	pecialist:	1/0	1/4	<u> </u>	2			
Title: Vice	Preside	nt/Gener		Approval Date: 8814 Expiration Date: N/A									
E-mail Addres	s: bbrac	ken@han]	.eypet:	coleum.com		Conditions of	Approval:			Attached			
Date: 7/27	/16		Phone.	32 684 805	51 P	emediatio	n per O.C.D.	. Rules	& Guid	elines			
Attach Additi		s If Necessa				DRIMIT RE	MEDIATION	PROF	POSAL	NO /	7//	2011	
						ATER THA	N: 918	116		O	KP.	2001	

## Patterson, Heather, EMNRD

From:

Sent:

Friday, August 05, 2016 9:47 AM

To:

Patterson, Heather, EMNRD

Subject:

RE: Hanley Petroleum

**Attachments:** 

Form C-141.pdf

Please see attached....hard copy to follow

## Brett K. Bracken

Vice President and General Manager Hanley Petroleum Inc. 415 W. Wall, Ste. 1500 Midland, TX 79701 432-684-8051 432-634-7504 cell

**From:** Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]

**Sent:** Wednesday, July 27, 2016 8:01 AM **To:** bbracken@hanleypetroleum.com

Cc: Bratcher, Mike, EMNRD; Cordero, Gilbert, EMNRD; Bayliss, Randolph, EMNRD; agroves@slo.state.nm.us

Subject: FW: Hanley Petroleum

Mr. Bracken,

Our field inspector sent these pictures of the State 32 #1 well operated by Hanley Petroleum. There appears to be a current spill, as well as some historic impact, and an active gas leak at this location. At this time, OCD requests a Form C-141 be submitted for this site. Please report any known volumes that may have been released, but if volumes are unknown, indicate that on the form. Remediation of the site will be required according to OCD rules and guidelines. OCD records indicate the site is situated on State surface, so NMSLO is being copied on this email.

If you have any questions or concerns, please contact me.

Thank you,

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Cordero, Gilbert, EMNRD Sent: Tuesday, July 26, 2016 3:11 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Subject: Hanley Petroleum

Attached are some pics of State 32 #001. API 30-015-29378. It appears they had a release and the red valve in pic #005 is open and blowing gas.

Thanks,

Gilbert Cordero Compliance Officer NMOCD District II Office 575.748.1283 ext.114 Cell 575.626.0830