### NM OIL CONSERVATION

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road. Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

### State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

AUG 1 1 2016
Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action													
NABIL	-225	36318			(	OPERAT	OR	<b>D</b>	Initial	Report		Final Report	
Name of Company Oxy Permian Ltd. 16096							asey Summers						
		ive, Midland		705		Telephone No. (575) 513-8289							
Facility Name TDC 8 State #001 Facility Type Well													
Surface Owner State Mineral Owner						API No. 30-015-32898							
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/V	West Line County				
L	8	195	29E		l				Eddy				
	<del>*************************************</del>	•	7	atituda N 32 6	• W 104 10449	6		<u>L</u>					
Latitude N 32.67265° Longitude W 104.10448°													
NATURE OF RELEASE													
Type of Release Produced water  Source of Release Internal corrosion of a 2.875" steel disposal line						Volume of		Volume Recovered 0 bbls  Date and Hour of Discovery					
Source of Release Thternal corrosion of a 2.875 steel disposal line						Date and Hour of Occurrence Date and Hour of Discovery 07/30/2016						У	
Was Immediate Notice Given?						If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD							
By Whom? Kathy Purvis @ BBC International Inc.						Date and Hour 08/01/2016 @ 12:36 pm							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
☐ Yes ⊠ No													
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
Internal corrosion of a 2.875" steel disposal line caused a leak of 7 bbls of produced water. No fluids were recovered and the line was repaired.													
Describe Area Affected and Cleanup Action Taken.*													
The affected area is approximately 100' x 65' on location around the well head. Remediation will be completed in accordance with an approved remediation plan from NMOCD.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
				e is true and comp nd/or file certain :									
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
reacting state, of topal tamp approximations.							OIL CONSERVATION DIVISION						
Signature: ///						Approved by Environmental Specialist:							
Printed Name: Casey Summers							Environmental S	peciansi	1/	W/2	<u></u>		
Title: NM Environmental Advisor						Approval Dat	te: 8   12   1	الما	Expiration	Date: N	/A		
E-mail Addre	ess: <u>Case</u>	y_Summers@	oxy.com			Conditions of	f Approval;			Attache	-d [7]		
Duy 8-11-16 Mars (575) 517 0700 PRO							emediation per O.C.D. Rules & Guidelines						
Date: (373) 313-0269 1155881T DEMEDIATION PROPOSAL NO												2016	
A LIGGER AGGILL	onui oneel	. 41 1766633 <b>0</b>	• ,		<u></u> /	ATER THA	N:_ <i>9/13</i>	IIL		0	ßKP	3825	

### Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>

Sent: Wednesday, August 10, 2016 1:32 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc: Casey\_Summers@oxy.com; jennifer\_duarte@oxy.com; cbrunson@bbcinternational.com;

'Ken Swinney'; jgilkey@bbcinternational.com

**Subject:** Initial C-141, TDC 8 State #001

Attachments: Initial C-141, TDC 8 State #001.pdf

Attached is the initial C-141 for a leak that occurred at the TDC 8 State #001 on 07/30/2016 in Eddy County, NM. Receipt notification and the RP number via email is greatly appreciated.

# **Kathy Purvis**

BBC International, Inc. 1324 W. Marland Blvd. Hobbs, NM 88240

Business: (575) 397-6388 Cell: (575) 441-8619

kathy@bbcinternational.com

#### Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>

**Sent:** Monday, August 01, 2016 12:36 PM

**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc: Casey\_Summers@oxy.com; jennifer\_duarte@oxy.com; 'Cliff P. Brunson';

kswinney@bbcinternational.com; jgilkey@bbcinternational.com;

kathy@bbcinternational.com

Subject: TDC 8 State #001

This is to inform you that Oxy Permian had a release at the TDC 8 State #001 on July 30, 2016. Oxy released 7 bbls of produced water due to internal corrosion of a 2.875" steel tubing disposal line. The preliminary reports shows the leak measuring 30' x 60' on location around the well head. No fluids were recovered. The release is located in U/L of Section 8, T195, R29E in Eddy County, NM. Driving directions: At the intersection of CR210 and NM360, go south on CR210 to Curry Comb Rd, go 3 miles to TDC sign, go right 1.5 mile, then take a left to the battery. GPS coordinates: N 32.67257° W 104.10420° API# 30-015-32898

## **Kathy Purvis**

BBC International, Inc. 1324 W. Marland Blvd. Hobbs, NM 88240

Business: (575) 397-6388 Cell: (575) 441-8619

kathy@bbcinternational.com