

# NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico  
Energy Minerals and Natural Resources

OCT 19 2016

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
RECEIVED accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

NAB1629841253

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294, Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Federal 23 #007H	Facility Type	Well

Surface Owner	BLM	Mineral Owner		API No.	30-015-39436
---------------	-----	---------------	--	---------	--------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	26	22S	31E					Eddy County, NM

Latitude N 32.36811° Longitude W 103.75084°

## NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 10 bbls produced water	Volume Recovered	0 bbls
Source of Release	Faulty fitting	Date and Hour of Occurrence	10/08/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	10/11/2016 @ 8:31 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A faulty fitting caused a leak of 2 bbls of oil and 10 bbls of produced water. Recovery was unachievable due to shallow leak depth. The fitting was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 100' x 165' on location around the well head. Remediation will be completed in accordance with a plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			<b>OIL CONSERVATION DIVISION</b>		
Printed Name:	Casey Summers	Approved by Environmental Specialist:			
Title:	NM Environmental Advisor	Approval Date:	10/24/16	Expiration Date:	N/A
E-mail Address:	Casey_Summers@oxy.com	Conditions of Approval:	Remediation per O.C.D. Rules & Guidelines		
Date:	10-19-16	Phone:	(575) 513-8289	Submitted <input type="checkbox"/>	
		SUBMIT REMEDIATION PROPOSAL NO			

\* Attach Additional Sheets If Necessary

LATER THAN: 11/16/16

2RD-3450

**Bratcher, Mike, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Wednesday, October 19, 2016 3:20 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'Tucker, Shelly'  
**Cc:** Casey\_Summers@oxy.com; Jennifer\_Hudgens@oxy.com;  
cbrunson@bbcinternational.com; kswinney@bbcinternational.com;  
jgilkey@bbcinternational.com  
**Subject:** Initial C-141, Federal 23 #007H  
**Attachments:** Initial C-141, Federal 23 #007H.pdf

Attached is the initial C-141 for a leak that occurred at the Federal 23 #007H on 10/08/2016 in Eddy County, NM. Receipt notification and the RP number via email are greatly appreciated.

**Kathy Purvis**

BBC International, Inc.  
1324 W. Marland Blvd.  
Hobbs, NM 88240  
Business: (575) 397-6388  
Cell: (575) 441-8619  
[kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

## **Patterson, Heather, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Tuesday, October 11, 2016 8:31 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'Tucker, Shelly'  
**Cc:** Casey\_Summers@oxy.com; Jennifer\_Hudgens@oxy.com;  
cbrunson@bbcinternational.com; kswinney@bbcinternational.com;  
jgilkey@bbcinternational.com; kathy@bbcinternational.com  
**Subject:** Federal 23 #007H

This is to inform you that Oxy Permian had a leak at the Federal 23 #007H on October 8, 2016. Oxy released 2 bbls of oil and 10 bbls of produced water due to a faulty fitting. The preliminary reports indicates the leak measures 100' x 200' on location at the well head. Recovery was unachievable due to a shallow spill depth. The release is located in U/L C, Section 26, T22S, R31E in Eddy County, NM. Driving directions: From the intersection of NM128 and C29(Red Rd), go North on Red Road approximately 7 miles to first lease road after Mills Ranch Road, turn left and go 1 mile to location. GPS coordinates: N 32.27055° W 103.85907° API# 30-015-39436

### **Kathy Purvis**

BBC International, Inc.  
1324 W. Marland Blvd.  
Hobbs, NM 88240  
Business: (575) 397-6388  
Cell: (575) 441-8619  
[kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)