							NIVI		JUNSER		N .	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II			ć	State of New Mexico					STA DISTR	RICT	Form C-141	
				Energy Mi	nerals	and Natural Resources			v 2 1 2(	316	Revised August 8, 2011	
811 S. First St.,	811 S. First St., Artesia, NM 88210			2							•	
District III				Oil C	Conser	vation Div	vision	Sub	mit I Copy	to approp	riate District Office in with 19.15.29 NMAC.	
1000 Rio Brazos Road, Aztec, NM 87410 District IV				1220 South St. Francis Dr.					ECEIVE		WITH 19,15.29 INWAC.	
1220 S. St. Francis Dr., Santa Fc, NM 87505					Santa Fe, NM 87505				ECEIVE			
<u> </u>									······································			
			Rela	ease Notific	atior	n and Co	orrective A	ctior	1			
DABIN	22-8	41630			OPERAT	FOR		🛛 Initia	l Report	Final Report		
Name of Company Cimarex Energy //12/183						Contact Christine Alderman						
Address 600 N Marienfeld Ste 600 Midland TX						Telephone No. 432-853-7059						
Facility Name Pintail 23 #8H												
racinty Name Pintan 25 #6FI						Facility Type production						
Surface Owner Mineral Owner									API No	. 30-015	-38657	
				1.004	TIO	N OF REI	EASE					
LOCATION OF RELEASE           Unit Letter         Section         Township         Range         Feet from the         Feet from the         East/West Line         County												
1												
<u> </u>	23	258	26E	_250		S	800		W	Eddy		
				Latitude_3	2.10874	4_Longitud	e -104.26932					
				NAT	URE	OF RELI	EASE					
Type of Release Produced water						Volume of Release 50 bbls Volume Recovered 2 bb					2 bbls	
Source of Release piping							our of Occurrence	cc Date and Hour of Discovery				
						11/20/2016			11/20/201	6		
Was Immediate Notice Given?						If YES, To Whom?						
	Yes 🗌 No 🔲 Not Required						d Shelly Tucker/Hcather Patterson/Mike Bratcher					
By Whom?			•			Date and Hour						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
🗌 Yes 🖾 No									MA		ONSERVATION	
If a Watercourse was Impacted, Describe Fully. ARTESIA DISTRICT											SIA DISTRICT	
		<u> </u>										
										NU	v <b>2 1</b> 2016	
Describe Cau	se of Proble	em and Reme	dial Actio	n Taken							·	
A 2" threaded							R	ECEIVED				
										<u> </u>		
Describe Are									1 .1			
The affected	area was pa	isture area and	i was appr	oximately 2' wide	e by 25'	long. We wil	Il delineate and su	ibmit a	work plan t	o remedia	te.	
I hereby certi	fy that the i	nformation of	iven above	is true and comp	lete to th	hest of my	knowledge and u	ndersta	nd that nurs	uant to N	MOCD rules and	
regulations al	l operators	are required t	o report a	nd/or file certain r	elease n	offications a	d perform correc	tive act	ions for rela	eases which	h may endanger	
public health	or the envir	connect The	accentan	ce of a C-141 repo	oreque h	NMOCD m	arked as "Final R	cport" d	loes not reli	cvc the or	erator of liability	
should their c	perations h	ave failed to	adequately	investigate and r	emediate	e contaminati	on that pose a three	cat to g	round water	surface v	vater, human health	
or the environ	ment. In a	ddition, NMC	CD accer	tance of a C-141	report d	oes not reliev	c the operator of i	respons	ibility for co	ompliance	with any other	
federal, state,					-			•		. <u> </u>		
					·		OIL CON	SERV	ATION	DIVISI	ON CHO	
Signature: Christine alderman									,/			
									1			
Printed Name: Christine Alderman							Environmental Sp	pecialis	t: // 2	be	n	
1 miles i tam	. Christine					-4		/^				
1		Title: ESH Supervisor						61	Expiration I	Date: N	/A	
Title: ESH S	upervisor					Approval Dat		¥		1		
		non@-!									/	
Title: ESH S E-mail Addre		nan@cimarex	com			Conditions of		₩ <b></b>		Attache	/	
E-mail Addre	ss: caldern										/	
· ·	ss: caldern 2016	Phone: 43	2-853-705	59							/	

## Patterson, Heather, EMNRD

From:Christine Alderman <calderman@cimarex.com>Sent:Monday, November 21, 2016 9:54 AMTo:Patterson, Heather, EMNRD; stucker@blm.gov; Price, HenryettaSubject:Pintail Fed 23 #8 (API 30-015-38657)Attachments:20161121104508129.pdf

All,

We had a produced water release at the above named lease 11/20/2016.

50 bbls were released and 2 bbls were recovered.

A 2"threaded fitting corroded and failed. The affected area was pasture and was approximately 2' x 25'.

1

Please see attached C-141.

Thank you.

**Christine Alderman** 

Cimarex Energy Co.

ESH Supervisor - Permian Basin Midland TX Cell - 432.853.7059

-----Original Message-----From: MidlandScanner@cimarex.com [mailto:MidlandScanner@cimarex.com] Sent: Monday, November 21, 2016 10:45 AM To: Christine Alderman <calderman@cimarex.com> Subject: Message from "RNP0026732E6735"

This E-mail was sent from "RNP0026732E6735" (Aficio MP C5501).

Scan Date: 11.21.2016 10:45:07 (-0600) Queries to: MidlandScanner@cimarex.com