NM OIL CONSERVATION

NOV 3 0 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

SARECETOR

Form C-141 Revised August 8, 2011

Support Edges to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action													
		<u> 30241</u>		PERAT		X	Initial	Report		Final Report			
Name of Co		Oxy Permia	Contact Casey Summers Telephone No. (575) 513-8289										
Address PO Box 4294; Houston, TX 77210 Telephone No. (575) 513-8289 Facility Name Pure Gold B Federal #004 Facility Type Well													
Surface Owner BLM Mineral Owner							API No. 30-015-27238						
Common on	<u></u>	* •		<u> </u>									
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
		•	31E	r cei iiom me	Notar.								
P	20	235	<u> </u>				Eddy						
Latitude N 32,28453° Longitude W 103,79344°													
NATURE OF RELEASE													
Type of Release Oil and produced water						Volume of Release 5 bbls oil, Volume 35 bbls produced water			/olume F	ume Recovered 20 bbls			
Source of Release Compromised flow line at the well head									Date and	d Hour of Discovery			
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required						If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM							
By Whom? Kathy Purvis @ BBC International Inc.						Date and Hour 11/21/2016 @ 4:25 pm							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Course of Destriction of Described to Table 2													
Describe Cause of Problem and Remedial Action Taken.*													
A compromised flow line at the well head caused a leak of 5 bbls of oil and 35 bbls of produced water. A vacuum truck recovered 20 bbls of fluids and the line was repaired.													
Describe Area Affected and Cleanup Action Taken.*													
The affected	The affected area is approximately 100' x 50' on location around the well head. Remediation will be completed in accordance with an approved												
remediation plan from NMOCD and the BLM.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have falled to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
	71	7-1-	~				OIL CON	SERVA	TION	DIVISI	<u>ON</u>		
Signature:	1/2	/	ļ	Approved by Environmental Specialist:									
Printed Name	: Casey	Summers	4										
Title: NM Environmental Advisor						Approval Date: 113016 Expiration Date: N/A							
E-mail Addr	E-mail Address: Casey Summers@oxy.com						Conditions of Approval:			Attached 🔽			
Date:	11-2	30-16	Phone	: (575) 513-828	39								
Attach Additi				. (2.5) 313 020						1	N	7	

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Wednesday, November 30, 2016 12:34 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov

Cc:

Casey_Summers@oxy.com; Jennifer_Hudgens@oxy.com; 'Cliff Brunson'; 'Ken Swinney'

Subject:

Initial C-141, Pure Gold B Federal #004

Attachments:

Initial C-141, Pure Gold B Federal #004.pdf

Attached is the initial C-141 for a leak that occurred at the Pure Gold B Federal #004 on 11/21/2016 in Eddy County, NM. Receipt notification and the RP number via email are greatly appreciated.

Kathy Purvis

BBC International, Inc. 1324 W. Marland Blvd. Hobbs, NM 88240

Business: (575) 397-6388 Cell: (575) 441-8619

kathy@bbcinternational.com

Patterson, Heather, EMNRD

Kathy Purvis <kathy@bbcinternational.com> From:

Monday, November 21, 2016 4:25 PM Sent: To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov

Casey_Summers@oxy.com; Jennifer_Hudgens@oxy.com; 'Cliff Brunson'; 'Ken Swinney'; Cc:

'Jennifer Gilkey'; kathy@bbcinternational.com

Subject: TPure Gold B Federal #0041

This is to inform you that Oxy Permian had leak at the Pure Gold B Federal #004 on November 21, 2016. Oxy released 5 bbls of oil and 35 bbls of produced water due to a compromised flow line at the well head. The preliminary report indicates the leak measures 65' x 40' on location. A vacuum truck recovered 20 bbls of fluids. The release is located in Section 20, T23S, R31E of Eddy County, NM. Driving directions: FROM CARLSBAD NM GO EAST ON HWY 280 TO HWY 31 TURN SOUTH ON HWY 31 GO TO HWY 128 GO TO MM 14 TO PURE GOLD ROAD TO THE SOUTH AND THE LOCATION IS .25 MILE ON RIGHT. GPS coordinates: N 32.28442 W 103.79297 API# 30-015-27238

Kathy Purvis

BBC International, Inc. 1324 W. Marland Blvd. Hobbs, NM 88240

Business: (575) 397-6388 Cell: (575) 441-8619

kathy@bbcinternational.com