

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

NM OIL CONSERVATION  
ARTESIA DISTRICT

MAR 12 2018

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

FAB1807457621  
NAB1807457743

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Energy Transfer #267256	Contact: Carolyn J. Blackaller
Address: 600 N. Marienfeld Street, Suite 700, Midland, TX 79701	Telephone No.: (817) 302-9766
Facility Name: Avalon Compressor Station	Facility Type: Natural Gas Compressor Station

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	20	26s	28e					Eddy

Latitude 32.02557 Longitude 104.11776 NAD83

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 7,840 Mcf	Volume Recovered: 0 Mcf
Source of Release: Blowdown due to cracked fitting on discharge line	Date and Hour of Occurrence: 3/6/2018 at 14:30	Date and Hour of Discovery: 3/6/2018 at 14:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver, Environmental Specialist, OCD - Artesia District II	
By Whom? Carolyn J. Blackaller, Sr. Environmental Specialist	Date and Hour: 3/8/2018 at 10:38	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

If a Watercourse was Impacted, Describe Fully.\*  
Not Applicable

Describe Cause of Problem and Remedial Action Taken.\*  
A cracked fitting on the discharge line was discovered. In order to make repairs, the line had to be isolated by blowing down the entirety of the discharge line. Once the line was blown down, a tee was welded on the fitting and the segment was fixed.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Carolyn J. Blackaller		OIL CONSERVATION DIVISION	
Printed Name: Carolyn J. Blackaller		Approved by Environmental Specialist: [Signature]	
Title: Sr. Environmental Specialist		Approval Date: 3/13/18	Expiration Date: N/A
E-mail Address: carolyn.blackaller@energytransfer.com		Conditions of Approval: FINAL	
Date: 3/9/2018 Phone: (817) 302-9766		Attached <input type="checkbox"/> 267256	

\* Attach Additional Sheets If Necessary



ENERGY TRANSFER

NM OIL CONSERVATION  
ARTESIA DISTRICT

MAR 12 2018

RECEIVED

March 9, 2018

State of New Mexico Oil Conservation Division, District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210

**RE: Form C-141 - Release Notification and Corrective Action**  
Energy Transfer Company  
Avalon Compressor Station

Ms. Crystal Weaver,

In accordance with 19.15.29 NMAC, please find enclosed Form C-141 – Release Notification and Corrective Action for the Energy Transfer Partners Avalon Compressor Station blowdown that occurred between 3/6/2018 and 3/8/2018. Should you have any questions or require additional information, please do not hesitate to contact me at (817) 302-9766 or at [carolyn.blackaller@energytransfer.com](mailto:carolyn.blackaller@energytransfer.com)

Sincerely,

Carolyn J. Blackaller  
Sr. Environmental Specialist