

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 18 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT II ARTESIA OGD
Submit copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

DAB1814251661 Nearburg OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Percussion Petroleum Operating, LLC 15742 Contact Eli Trevino

Address 919 Milam Street, Suite 2475 Houston, TX 77002 Telephone No. (575) 499-3993

Facility Name Huber 3 Federal #1 Facility Type Federal

Surface Owner Federal Mineral Owner Federal API No. 30-015-23958

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	3	20S	25E	1980'	South	1980'	East	Eddy

Latitude 32.6006737 Longitude -104.4705048 NAD83

NATURE OF RELEASE

Type of Release Produced oil and water Volume of Release 30bbls 20bbl PW Volume Recovered 28bbls 20bbl PW

Source of Release Water tanks Date and Hour of Occurrence 5/16/18 at 4:30 PM Date and Hour of Discovery 5/16/18 at 4:30 PM

Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required If YES, To Whom? Mike Bratcher (NMOCD) and Crystal Weaver (NMOCD)

By Whom? Toby Rhodes Date and Hour 5/17/18 at 4:30 PM

Was a Watercourse Reached? ☐ Yes ☒ No If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.*
No watercourse impacted.

Describe Cause of Problem and Remedial Action Taken.*
The subject well has been plugged, but the battery is still active for other wells. An equalizing line plugged at the battery, which caused a tank to overflow.

Describe Area Affected and Cleanup Action Taken.*
Approximately 30bbls (10bbls oil and 20bbls water) overflowed from the tank. All the fluid was contained within the containment area. A vacuum truck was used to pick up the standing fluid on the ground. Recovered fluid was 8-9bbls oil and 15-20bbls water. We will have a backhoe dig out the containment soil down to clean soil. The containment soil will be disposed of in accordance to local, state, and federal law statutes.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Michael Martin OIL CONSERVATION DIVISION

Printed Name: Michael Martin Approved by Environmental Specialist: Mike Bratcher

Title: Petroleum Engineer Approval Date: 5/22/18 Expiration Date: NIA

E-mail Address: Michael@percussionpetroleum.com Conditions of Approval: See attached Attached ☒ APP-4762

Date: 5/18/2018 Phone: (713) 429-4249

* Attach Additional Sheets If Necessary

Operator/Responsible Party,

The OCD has received the form C-141 you provided on 5/21/2018 regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number ARP-4762 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District 2 office in ARTESIA on or before 6/21/2018. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief
1220 South St. Francis Drive
Santa Fe, New Mexico 87505
505-476-3465
jim.griswold@state.nm.us

Bratcher, Mike, EMNRD

From: Michael Martin <Michael@percussionpetroleum.com>
Sent: Friday, May 18, 2018 3:04 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc: Lupe Carrillo; Toby Rhodes
Subject: RE: 30-015-23958 Huber Federal #1 Location - Spill
Attachments: Huber 3 Federal #1 C-141.pdf

See attached for the C-141 for the Huber 3 Federal #1 location.

Thanks,
Michael Martin
(281) 974-6817
Michael@percussionpetroleum.com

From: Toby Rhodes
Sent: Thursday, May 17, 2018 5:47 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Eli Trevino <eli@percussionpetroleum.com>; John Campbell <John@percussionpetroleum.com>; Lelan Anders <lelan@percussionpetroleum.com>; Lupe Carrillo <Lupe@percussionpetroleum.com>; Michael Martin <Michael@percussionpetroleum.com>; Tracy Strain <tracy@percussionpetroleum.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: Clint White <ClintW@percussionpetroleum.com>; Michael Martin <Michael@percussionpetroleum.com>; Eli Trevino <eli@percussionpetroleum.com>; Lupe Carrillo <Lupe@percussionpetroleum.com>; John Campbell <John@percussionpetroleum.com>; Jordan Blount <jordan@percussionpetroleum.com>
Subject: 30-015-23958 Huber Federal #1 Location - Spill

The subject well has been plugged but the battery is still active for other wells. An equalizing line plugged on the battery causing a tank to overflow around 4:30 PM on May 16, 2018. Approximately 10 barrels of oil & 20 barrels of water overflowed from the tank. All the fluid was contained within the containment area. A vacuum truck was used to pick up the fluid. Recovered fluid was 8-9 barrels of oil and 15-20 barrels of water. Detailed report to follow.

Toby Rhodes
VP of Production

Percussion Petroleum, LLC
919 Milam St. Suite 2475
Houston, TX 77002
Main: 713.518.1331
Mobile: 575.748.5359
Toby@PercussionPetroleum.com

